30.06.2018

BLOCK	STATUS AS ON 30.06.2018				
A1 BLOCK	 Piling work 100% completed. Earth work excavation for Pile Cap works on progress. 				
BLOCK	STATUS AS ON 30.06.2018				
A2 BLOCK	 Piling work 100% completed. Earth work excavation for Pile Cap works on progress. 				
BLOCK	STATUS AS ON 30.06.2018				
B1 BLOCK	 Piling work 100% completed. Pile cap casting 100% completed. Columns up to stilt 100% completed. Columns upto First floor level 50% completed Barbending & shuttering work on progress for balance 50% Columns upto First floor Level. Barbending & shuttering work for 1st Half of First floor level slab on progress. 				
BLOCK	STATUS AS ON 30.06.2018				
B2 BLOCK	 Piling work 100% completed. Earth work excavation for Pile Cap works on progress. PCC for pile cap on progress 				
BLOCK	STATUS AS ON 30.06.2018				
C1 BLOCK	 Piling work 100% completed. Pile cap casting 100% completed. Columns up to stilt 100% completed. Columns upto First floor level 50% completed Barbending & shuttering work on progress for balance 50% Columns upto First floor Level. First floor level slab First half Concrete 50% Completed. Barbending & shuttering work for Second half First floor level slab 50% on progress. 				



BLOCK	STATUS AS ON 30.06.2018				
C2 BLOCK	 Piling work 100% completed. Earth work excavation for Pile Cap works on progress Barbending & shuttering work for pile cap on progress. Pile Cap work 35% completed. 				
BLOCK	STATUS AS ON 30.06.2018				
C3 BLOCK	 Piling work 100% completed. Earth work excavation for Pile Cap works on progress. 				
BLOCK	STATUS AS ON 30.06.2018				
D1 BLOCK	 Piling work 51% completed. Balance 49% Piling work on Progress. Barbending work for pile on progress. 				
BLOCK	STATUS AS ON 30.06.2018				
D2 BLOCK	 Piling work 100% completed. Pile cap casting 100% completed. Columns up to stilt 100% completed. Columns upto First floor level 50% completed Barbending & shuttering work on progress for balance 50% Columns upto First floor Level. First floor level slab First half Concrete 50% Completed. Barbending & shuttering work for Second half First floor level slab 50% on progress. 				
BLOCK	STATUS AS ON 30.06.2018				
D3 BLOCK	 Piling work 100% completed. Pile cap casting 50% completed. Columns up to stilt floor level 50% completed. Earth work excavation for Pile Cap works on progress. PCC for pile cap on progress. Barbending & shuttering work for pile Caps on progress. Barbending & shuttering work for Stilt floor level Columns on progress. 				
BLOCK	STATUS AS ON 30.06.2018				
COMMUNITY HALL	 Piling work 100% completed. Earth work excavation for Pile Cap works on progress PCC for pile cap on progress Barbending & shuttering work for pile caps on progress. 				



PHOTOGRAPHS OF C1 BLOCK AS ON 30.06.2018

In Block C1 First floor level slab .First half concrete completed, Second half Shuttering Process.




In Block C2 Excavation work, Shuttering for Short Column and for Pile cap Works on progress.





In Block C2 Concreting for Pile cap Works on progress.



In Block C3 Excavation work for Pile Cap works on progress.



In Community Centre excavation for pile cap works & pile chipping up to cut off level on progress.



In Block B1 shuttering work for First floor level slab is in progress.



In Block B2 Excavation Work for Pile Cap Works on process.



In Block D1 Pilling Work in Process





In Block D2 First Floor Level - First half Concrete Casting Completed.



In Block D2 -Shuttering & Bar bending Works on Progress for Second half of First Floor Level Slab



In Block D3 Pile Cap Concrete Works are in Progress.



In Block A1 & A2 Excavation works for Pile Cap Works are in progress.








BIRD EYE VIEW PHOTOGRAPHS OF CHENNAI PHASE-III PROJECT

VIEW OF ENTRANCE FROM MAIN ROAD SHOWING MAIN GATE, COMMUNITY CENTRE & PARK DEVELOPED BY AVADI MUNICIPALITY ON OUR OSR LAND





VIEW OF TYPE A - BLOCKS A1 & A2



VIEW OF TYPE B - BLOCKS B1 & B2



VIEW OF TYPE C - BLOCKS C1, C2 & C3



VIEW OF TYPE D - BLOCKS D1 , D2 & D3



QUALITY CONTROL

$\frac{\text{DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS CONDUCTED}}{\text{AT SITE:}}$

Sl.No.	Materials	Source from	Test Done	Result	
1	M-Sand	Sriperambathur, Kanchipuran (Dt)	Each Truck	Sieve Analysis & Silt content	
2	Coarse Aggregate (20mm)	Sriperambathur, Kanchipuran (Dt)	Each Truck	Sieve Analysis	
3	Coarse Aggregate (12mm)	Sriperambathur, Kanchipuran (Dt)	Each Truck	Sieve Analysis	
4	Cement	Third party testing is being done.			
5	Steel	Third party testing is being done.			
6	Pile Integrity	Third party testing is being done.			
7	Soil Compaction	Third party testing is being done.			
8	RCC cubes are being tested and Register is being maintained.				
9	Slump test conducted at site to insure workability if concrete.				



PHOTOGRAPH OF QUALITY CONTROL AT SITE

Concrete Cube Compressive Strength Testing



20mm & 12mm Aggregate Sieve Analysis Testing



Fine Aggregate Sieve Analysis Testing

