1. PACKAGE-II

30-JUNE- 2017

PACKAGE-II	STATUS AS ON 30/06/2017				
Block D03	• All R.C.C. work completed up to basement roof slab level.				
	• 50% Stilt Roof slab casted.				
	Total Columns casted upto soffit of Stilt Roof beams.				
Current Month	Balance 50% of Stilt Roof slab casted. Total (100%)				
Activity	First Floor Slab 100% casting done.				
	• 20 Columns casted upto soffit of 2 nd Floor Roof beams.				
Block D04	• All work upto pile caps completed.				
	 Both the Staircases casted upto Basement Roof level. 				
	• All columns casted up to soffit of basement roof beams.				
	Basement Roof Slab 25% casted.				
Current Month	Basement Roof Slab 50% casted.				
Activity	Basement Roof slab shuttering work for Remaining one flat is				
	in progress.				
	Total 21 Columns casted upto Soffit of Stilt Roof beams.				
Block D05	• All work upto pile caps completed.				
	• All columns casted up to soffit of basement roof beams.				
Current Month	• Single flight Reinforcement binding of Both the Staircases				
Activity	done.				
Block D06	• All work up to pile caps completed.				
	• Total 64 columns casted up to soffit of basement roof beam				
Current Month	bottom.				
Activity	Balance 4 columns casted upto soffit of Basement Roof beam bottom.				
Block D07	All work upto Stitch slab and grade beams completed.				
DIOCK DU/	 Total Pile Caps Casted. 				
Current Month	Total 49 Columns casted upto a height of 2400mm.				
Activity	Remaining Columns Reinforcement binding work complete				
Block D08	• 100% P.C.C. for foundation work completed.				
210011200	• 50% Stitch slab and grade beams casted.				
Current Month	Balance Stitch slab 50% & 50% Grade Beams casted.				
Activity	• 100% Pile Caps casted.				
Non Tower	• Total 549 nos. of piles casted out of 593 nos.				
	• 20% P.C.C. for foundation work completed.				
	• 5% of Stitch slab casted.				
Current Month	• 5.57% P.C.C. for foundation work completed (Total 25.57%)				
Activity	& further work in Progress.				
-	 6% of Stitch slab casted. 				
	Balance 44 Piles Casted.				
Retaining Wall	• Total 68 nos. of piles casted out of 72 nos.				
	 Retaining wall footing of length 40 mtrs. Retaining wall of length 40 mtr casted (1st lift). 				





Current Month	Retaining wall of length 17mtrs casted (2nd lift).				
Activity	Balance 4 Piles casted. (Total 72 Piles i.e. 100% completed).				
	• Reinforcement binding work for 2 nd lift is in progress				

PHOTOGRAPHS OF PACKAGE-II on 30thJUNE-2017

BLOCK D-04 BASEMENT SLAB SHUTTERING IS IN PROGRESS







BLOCK D-04 STILT FLOOR SLAB SHUTTERING IS IN PROGRESS







BLOCK D-03 2ND FLOOR SLAB SHUTTERING WORK IS IN PROGRESS.







BLOCK D-06 COLUMNS CASTING 100% COMPLETED.







2. PACKAGE-III

PACKAGE-III	STATUS AS ON 30/06/2017		
Block C06			
Current Month	80% Excavation work completed.		
Activity	Layout for piling in progress.		
Block C07			
Current Month Activity	80% Excavation work completed.		
Block C08			
Current Month Activity	80% Excavation work completed.		
Block C01			
Current Month	50% Excavation work completed.		
Activity			
Block C02			
Current Month Activity	80% Excavation work completed.		






EXCAVATION WORK IN BLOCK C06, C07 & C08 COMPLETED.







EXCAVATION WORK IN BLOCK C06, C07 & C08 COMPLETED.







3. PACKAGE-IV

PACKAGE-IV	STATUS AS ON 30/06/2017					
Block A01	All civil work completed upto Pile caps.					
Current Month Activity	 80% columns casting completed for basement roof. 50% Basement slab casting work completed. 					
Block B04	• Stilt roof slab casting 100% (8 flats) completed.					
Current Month	100% Columns casting of First floor completed.					
Activity	 First floor roof slab 50% (4 flats) shuttering & steel binding work completed. 					
Block B05	• Second floor roof slab casting 100% (8 flats) completed.					
Current Month Activity	• 100% Steel binding completed & casting started of third floor columns.					
	 Shuttering work for third floor roof slab started. 					
Block C13	• First floor roof slab casting 100% (4 flats) completed.					
Current Month Activity	 50% Steel binding & casting of second floor columns is completed. 					
Block C14	• Second floor roof slab casting 100% (4 flats) completed.					
Current Month Activity	• 50% columns casting of third floor completed.					
Block C03	• Total 195 nos. of piles casted out of 195.					
~ ~ ~ ~ ~ ~	Routine pile testing completed.					
Current Month	Piling work completed. 50% DCC much completed					
Activity	50% PCC work completed. Total 44 page of piles costad out of 104					
Block C04	• Total 44 nos. of piles casted out of 194.					
Current Month Activity	• No work done.					
Block C05	• Total 120 nos. of piles casted out of 195.					
Current Month Activity	Piling work is in progress.					
Non Tower	• Total 630 nos. of piles casted out of 825.					
	• 106 nos. Pile casting for STP completed.					
	800 sqm slab casting of extended basement completed.					
Current Month Activity						
1 scuvity	 Kota stone water proofing work on outer side of retaining 					
	wall is in progress.					
Permission for	Required permission obtained from the Mining Authority Greater					
Excavation	Noida on12th April 2017.					





PHOTOGRAPHS OF PACKAGE-IV on 30th June2017


BLOCK B053RD FLOOR COLUMNS CASTING 50% COMPLETED.







BLOCK C14 3rd FLOOR COLUMNS CASTING 40% COMPLETED








BLOCK C13 3rd FLOOR SLAB SHUTTERING IN PROGRESS







BLOCK C05 PILING WORK IN PROGRESS







4. PACKAGE-V

PACKAGE-V	STATUS AS ON 30/06/2017				
Block B01	• 50% casting of 2 ¹¹⁰ floor slab competed.				
	• Sample flat Brick work upto lintel level is completed.				
Current Month	 50% casting of 2nd floor slab completed. Total (100%) 				
Activity	• 100 % 3 ^{ru} Floor slab Casting done.				
	• 50% columns casted up to soffit of 3 rd floor Roof Beam				
	bottom.				
	 Balance Sample flat Brick work is completed. Total (100%) Total 50% Brick work in stilt floor done. 				
	 Total 3 Flats Brick work in First floor is completed. 				
Block B02	50% casting of Stilt floor slab completed.				
DIOCK DO2	50% casting of Still hoor side completed.				
Current Month	Balance 50% casting of Stilt floor slab completed. Total				
Activity	(100%).				
	• 100% First floor slab casted.				
	• 75 % Columns casted at 2nd floor level.				
	50% Brick work in Stilt floor done.				
Block B03	• 50% casting of Basement Roof slab done.				
Current Month	Balance 50% casting of Basement Roof slab done. Total				
Activity	(100%).				
	 50% Columns casted at Stilt floor level. 				
Block C15	• 75% casting of Stilt floor slab completed.				
Current Month	Balance 25% casting of Stilt floor done. Total (100%)				
Activity	• 75% casting of First floor done.				
	 50% Columns casted at 2nd floor level. 				
Block C16	• 50% casting of Basement roof slab done.				
Current Month Activity	• Balance 50% casting of basement roof slab is completed. Total (100%).				
·	 100% columns casted upto Soffit of Stilt Roof Beam bottom. 				
	 Shuttering work of Stilt Roof slab is in progress. 				
Non Tower	• Piling work is completed.				
	• 97% stitch slab casting completed.				
	• 75 % columns casting completed.				
Current Month	• 3 % of P.C.C work for foundation done.				
Activity	• 1% of stitch slab casting done.				
Retaining Wall	• Piling work is completed.				
	• Casting of retaining wall upto a length of 140 mtr completed.				
Current Month	Casting of Retaining wall footing upto a length of 40 mtrs				
Activity	done.				





PHOTOGRAPHS OF PACKAGE-V on 30Th JUNE-2017

BLOCK C-15 STILT FLOOR SLAB SHUTTERING IN PROGRESS.







BLOCK B-01 3RD FLOOR SLAB REINFORCEMENT BINDING WORK IS IN PROGRESS.







BLOCK B-014TH FLOOR SLAB SHUTTERING WORK IN PROGRESS







BLOCK C-151ST FLOOR SLAB SHUTTERING WORK IS IN PROGRESS







QUALITY CONTROL

DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS CONDUCTED AT SITE:

S. No	Materials	Source from	Test Date	Tests done	Result		
1	Coarse Sand	Bajpur		Each truck	Sieve/Silt		
2	Coarse Aggregate	Nagal		Each truck	Sieve Analysis		
3	Fine Sand						
4	Cement	Third party testing is being done					
5	Steel	Third party testing is being done					
6	RCC Cubes are being tested and Register is being maintained.						
7	Slump test conducted at site to insure workability if concrete.						





PHOTOGRAPHS TAKEN DURING QUALITY CONTROL AT SITE

20mm & 10mm Aggregate Testing







SLUMP TESTING







CUBE TESTING







TESTING OF COARSE SAND





