31st-MAY -2021

PACKAGE-II	STATUS AS ON 31/05/2021
Up to Last Month	• External painting work 1 <sup>st</sup> coat 3% completed. (Total 98%).
Block D01	• 100% Fire shaft door Fixing work completed.
	• 100% False ceiling framing in Toilet's work completed.
	• 15% Chinaware fixing work completed.
	• 100% staircase first coat paint work completed.
Current Month	• External painting work 1st coat 3% completed. (Total 98%).
Activity	• 16% Chinaware fixing work completed.
	Toilet ceiling painting work completed.
Up to Last Month	• External painting work 1 <sup>st</sup> coat 05% completed. (Total 80%).
Block D02	<ul> <li>Meter board panel fixing work completed.</li> </ul>
	• 100% Fire shaft door Fixing work completed.
	• 100% staircase first coat paint work completed.
	• 100% False ceiling framing in Toilet's work completed.
Current Month	• External painting work 1st coat 05% completed. (Total 80%).
Activity	Toilet ceiling painting work completed.
<b>Up to Last Month</b>	• External painting work 25% completed. (Total 75%).
Block D03	Meter board panel fixing work completed.
	• 100% Fire shaft door fixing work completed.
	• 100% staircase first coat paint work completed.
Current Month	• External painting work 25% completed. (Total 75%).
Activity	• Toilet ceiling painting work completed.
	• Up to 11th floor false ceiling framing work completed.
<b>Up to Last Month</b>	• External painting work 35% completed. (Total 55%).
Block D04	• 100% Fire shaft door fixing work completed.
Current Month Activity	• External painting work completed. (Total 57%)
Up to Last Month	• 100% Stilt floor VDF flooring completed.
Block D05	• 90% Balcony SS Railing fixing work completed.
	• 55% Aluminum door window frames fixing work completed.
	• 25% Aluminum door window glazing fixing work completed.
	• Lift door, car body and motor location work completed.
Current Month	92% Balcony SS Railing fixing work completed.
Activity	• 95% Aluminum door window frames fixing work completed.
	• 65% Aluminum door window glazing fixing work completed.
	• Main entry door shutter fixed from 2 <sup>nd</sup> to 14 <sup>th</sup> floor.
	Main staircase railing first coat paint work completed.
	• Stilt floor wing -1 internal plaster work completed.





CGE	WHO – GREATER NOIDA PROJECT
<b>Up to Last Month</b>	• 14 <sup>th</sup> floor slab casting work completed.
Block D06	• 100% Stub & Mumty Columns casting work completed.
	• 5 <sup>th</sup> floor to 9 <sup>th</sup> floor Brick completed. (Total 100%).
	• 10 <sup>th</sup> floor to 12 <sup>th</sup> floor Brick work 90% completed.
	• 3 <sup>rd</sup> floor to 7 <sup>th</sup> floor Internal Plaster work completed. (Total 100%).
	8 <sup>th</sup> floor Internal Plaster work completed. (Total 60%).
	• Up to 8 <sup>th</sup> floor Door frames fixing completed.
	• Internal cPVC piping work completed up to 8 <sup>th</sup> floor.
	• Electrical wall conduiting work completed up to 8 <sup>th</sup> floor.
	Balcony RCC wall casted up to 5 <sup>st</sup> floor.
	POP cornice work completed up to 5 <sup>th</sup> floor.
Current Month	• 13 <sup>th</sup> floor Brick completed. (Total 100%).
Activity	• 9th floor Internal Plaster work completed. (Total 100%).
	<ul> <li>Up to 11<sup>th</sup> floor Door frames fixing completed.</li> </ul>
	<ul> <li>Internal cPVC piping work completed up to 8<sup>th</sup> floor.</li> </ul>
	• Electrical wall conduiting work completed up to 11 <sup>th</sup> floor.
	<ul> <li>Balcony RCC wall casted up to 8<sup>st</sup> floor.</li> </ul>
	<ul> <li>POP cornice work completed up to 5<sup>th</sup> floor.</li> </ul>
Un to Lost Month	
Up to Last Month Non-Tower	• APP membrane water proofing work 600 Sq. m completed. (Total 94%).
TVOII-TOWCI	• APP membrane water proofing screeding work 600 Sq. m completed. (Total 94%).
	<ul> <li>Green area pressure Guniting waterproofing in front of blocks D-02 &amp; D-</li> </ul>
	03 completed.
	• Green area Drain board fixing work completed front of blocks D-01, D-2
	& D-03.
	PCC in Road's area front of blocks D-01, D-02 & D-03 is completed.
	• Front portion of blocks D-02, D-3, D-04 & D-05 development work is in
	progress.
	Garden hydrant piping work is in progress.
	• Ventilation Cut out Polycarbonate sheet covering and Aluminium louvers work 90% completed.
	• Grass paver fixing work completed near block D01, D02 & D03.
	Ramp-5 APP Membrane sheet fixing work in progress.
	• 100 R/M drain brick work completed. (-750 lvl)
	• Chequered tile fixing work in progress near block D01. (Central Park)
	• Feature wall brick completed in front of block D05.
	• Kerb stone fixing work in progress near block D04 & D05. (Between
	package II & III park)
	1 1 U I'- /





Current Month	• 60% Green area pressure Guniting waterproofing central park.
Activity	• 500 sqm PCC work completed for green area pressure Guniting waterproofing in back side of block D06.
	• PCC in Road's area front of blocks D-01, D-02 & D-03 is completed.
	• Front portion of blocks D-02, D-3, D-04 & D-05 development work is in progress.
	• Garden hydrant piping work is in progress.
	• Ventilation Cut out Polycarbonate sheet covering and Aluminium louvers work 90% completed.
	• Grass paver fixing work completed near block D01, D02, D03& D04.
	• Ramp-5 APP Membrane sheet fixing work completed.
	• 80 R/M drain brick work completed. (-750 lvl)
	• 60% Chequered tile fixing work in progress central park
	<ul> <li>Kerb stone fixing work in progress near block D04 &amp; D05. (Between package II &amp; III park)</li> </ul>
	• Kerb stone fixing work in progress back side of Block D06.
	• Steel binding work in progress for road VDF in front and back side
	of Block D01 & D02.
	• Soil dressing, preparation work and Plantation work in progress.
Up to Last Month	Boundary wall Putty work completed.
Retaining Wall &	Boundary wall Railing painting work completed.
Boundary wall	
Current Month	
Activity	





# PHOTOGRAPHS OF PACKAGE-II on 31st MAY -2021

#### VIEW OF BLOCK D01,02,04,05,06 & EXTERNAL DEVELOPMENT







#### **GREEN AREA DEVELOPMENT BLOCK D01,02,03**







#### **CENTER PARK DEVELOPMENT WORK IN PROGRESS**







### BLOCK D06 ALL SLAB CASTING WORK COMPLETED.







PACKAGE-III	STATUS AS ON 31/05/2021
Up to Last Month Block C01	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring &amp; switches completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>Up to Level 12: Internal primer work completed.</li> <li>50% External First coat Paint work completed.</li> <li>Lift bulk head light point wiring completed.</li> <li>Lift car body work is on progress.</li> </ul>
Current Month Activity	<ul> <li>Level 13&amp;14: Internal primer work completed.</li> <li>60% External First coat Paint work completed.</li> <li>Lift earthing GI strip work completed.</li> <li>Lift car body and motor location work completed.</li> <li>Lift cladding work is on progress.</li> <li>Fire fighting frame &amp; Common area louvers completed.</li> </ul>
Up to Last Month Block C05	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI&amp;CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100%: Internal primer &amp; 1st coat paint work completed.</li> <li>70% External First coat Paint work completed.</li> <li>Up to Level 12: common area First coat paint work in progress.</li> <li>Lift stone cladding work completed.</li> <li>Lift bulk head light point wiring completed.</li> <li>Lift car body and motor location work completed.</li> <li>Lift earthing GI strip work completed.</li> </ul>
Current Month Activity	<ul> <li>90% External First coat Paint work completed.</li> <li>Level 13&amp;14: Common area &amp; Stilt First coat paint work completed.</li> </ul>





	CGEWHO – GREATER NOIDAT ROJECT
Up to Last Month  Block C-06	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI&amp;CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100%: Internal primer &amp; 1st coat paint including common area work completed.</li> <li>70% External First coat Paint work completed.</li> <li>Lift stone cladding work completed.</li> <li>Lift bulk head light point wiring completed.</li> <li>Lift car body and motor location work completed.</li> <li>Lift earthing GI strip work completed.</li> </ul>
Current Month Activity	<ul> <li>90% External First coat Paint work completed.</li> <li>Silicon filling in Aluminium door window is on progress.</li> </ul>
Up to Last Month Block C07	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI&amp;CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Flat internal electrical wiring, switches &amp; MCB completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>100%: Internal primer &amp; 1st coat paint including common area work completed.</li> <li>75% External First coat Paint work completed.</li> <li>Lift stone cladding work completed.</li> <li>Lift bulk head light point wiring completed.</li> <li>Lift car body and motor location work completed.</li> <li>Lift earthing GI strip work completed.</li> </ul>
Current Month Activity	<ul> <li>95% External First coat Paint work completed.</li> <li>Silicon filling in Aluminium door window is on progress.</li> </ul>





	CGEWHO – GREATER NOIDA PROJECT
Up to Last Month	<ul> <li>Level 15(Terrace): 100% slab casting and all structure work completed.</li> <li>Level 14: Brick work completed.</li> </ul>
Block C08	<ul><li>Level 14: Door frame completed.</li><li>Level 14: Electrical wall conduit completed.</li></ul>
	Level 14: Internal plaster completed.
	• Level 12: POP Cornice work in progress.
	<ul><li>100% External plaster work completed.</li><li>External wall putty work in progress.</li></ul>
	<ul> <li>Level 14: Internal plumbing (CPVC) completed.</li> </ul>
	Level 09 to 11: External & internal plumbing (CI) work completed.
	• Level 12: External & internal plumbing (CI) work is on progress.
	Lift Material received at site.
	• 30% External wall putty work completed.
Current Month	<ul> <li>Level 13&amp;14: Water proofing completed.</li> </ul>
Activity	• Level 01 to 06: Wall tile (Toilet & kitchen) completed.
	• Level 07: Wall tile (Toilet & Kitchen) is on progress.
	• Level 01 to 05: Floor tile completed.
	• Level 06: Floor tile is on progress.
	<ul> <li>Level 12 to 14: External &amp; internal plumbing (CI) work completed.</li> <li>Terrace coba work is on progress.</li> </ul>
	Level 15(Terrace): 100% slab casting completed.
Up to Last Month	Above terrace over head tank wall casted.
DI 1 C00	Level 14: Brick work completed.
Block C09	• Level 11: Door frame completed.
	• Level 12: Door frame is on progress.
	<ul><li>Level 14: Electrical wall conduit completed.</li><li>Level 14: Internal plaster completed.</li></ul>
	<ul> <li>External plaster is on progress.</li> </ul>
	<ul> <li>Level 09,10&amp;11: Internal plumbing (cPVC) completed.</li> </ul>
	• Level 12: Internal plumbing (cPVC) is on progress.
Current Month	• Level 15(Terrace): 100% slab casting completed.
Activity	<ul><li>Above terrace over head tank wall casted.</li><li>Level 14: Brick work completed.</li></ul>
11001,103	• Level 14: Brick work completed. • Level 13: Door frame completed.
	• Level 14: Door frame is on progress.
	• Level 14: Electrical wall conduit completed.
	• Level 14: Internal plaster completed.
	• 25% External plaster is on progress.
	• Level 12: Internal plumbing (cPVC) completed.
	• Level 13: Internal plumbing (cPVC) is on progress.





Up To Last Month Block C10	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI&amp;CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter (Teak) &amp; staircase marble completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> </ul>
Current Month Activity  Up to Last Month Block C11	<ul> <li>40% External paint completed.</li> <li>100% Terrace brick coba.</li> <li>Common area putty is on progress.</li> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>Lift bulk head light point wiring completed.</li> <li>Lift car body work is on progress.</li> </ul>
Current Month Activity	<ul> <li>25% External First coat Paint work completed.</li> <li>Lift car body work completed</li> <li>Level 13&amp;14: Flat internal electrical wiring work completed.</li> </ul>

Up to Last Month Block C12	<ul> <li>100% RCC work completed.</li> <li>100% Tile work CI, GI &amp; CPVC work completed.</li> <li>100% M.S staircase &amp; S.S balcony Railing work completed.</li> <li>100% Aluminum Door window &amp; Louvers fixing completed.</li> <li>100% Door shutter &amp; staircase marble completed.</li> <li>100% Internal POP cornice &amp; Wall putty completed.</li> <li>Lift bulk head light point wiring completed.</li> <li>Lift car body and motor location work completed.</li> <li>Lift stone cladding work completed.</li> </ul>
Current Month Activity	<ul> <li>60% External painting work completed.</li> <li>Internal electrical wiring completed.</li> <li>Internal primer is on progress.</li> <li>Expansion joint B/W and plaster completed.</li> <li>Common area louvers and fire fighting frame completed.</li> </ul>





Up to last month	LIC Touls western and of the western and of the second of
UG Tank	• U.G. Tank water proofing work is on progress.
Current Month Activity	• U.G. Tank Tile work is on progress.
Up to last month  Non-Tower	<ul> <li>Stitch slab casting completed. (Total 18571/18731) Sqm</li> <li>Circular column casting completed. (Total 329/339) Nos.</li> <li>Basement non-tower slab casting completed Total (18731/18731) Sqm</li> <li>Retaining wall casting completed (277/294) m</li> <li>Boundary wall casted (277/277) RMT</li> <li>Basement plaster (18030/18731) Sqm.</li> <li>Basement PCC for VDC flooring (17760/20840) sqm</li> <li>Non tower slab APP membrane water proofing (13600/20700) sqm</li> <li>Amphitheater Granite fixing work completed.</li> <li>NP2 pipe laying for sewage work completed.</li> <li>Harvesting pit brick completed.</li> </ul>
Current Month Activity	<ul> <li>Non tower slab APP membrane water proofing 2100 sqm. (15700/20700)</li> <li>Kerb stone fixing work in progress.</li> <li>Drain brick work in progress.</li> <li>IGL brick work in progress.</li> <li>Planter &amp; Drain brick wall Granite fixing work in progress.</li> <li>Grass paver near block C05, C06 &amp; C07 work in progress.</li> <li>NP2 pipe laying for sewage work completed.</li> <li>Harvesting pit brick completed.</li> <li>HDPE pipe work garden hydrant work in progress.</li> <li>External firefighting line laying work in progress.</li> <li>Basement fire fighting work in progress.</li> <li>MS frame fixing work completed of cut out. (19/19) Nos</li> <li>Basement VDC Flooring 210 Sqm</li> <li>Basement plaster 500 Sqm. (18530/18731) Sqm.</li> </ul>





# PHOTOGRAPHS OF PACKAGE-III on 31st-MAY -2021

#### **BIRD EYE VIEW OF PROJECT**







# BLOCK C08 & C09 EXTERNAL PUTTY AND PLASTER WORK IN PROGRESS.







### BLOCK C05,06,07 EXTERNAL DEVELOPMENT WORK IN PROGRESS.







#### **CENTER PARK DEVELOPMENT WORK IN PROGRESS.**







PACKAGE-IV	STATUS AS ON 31/05/2021
Up to Last Month	• 95%External Paint 1st coat work completed.
Block A01	One Staircase railing one coat paint work completed.
	Staircase flush door fixing work completed.
	Aluminium door windows silicon filling work completed.
	Common area light fixture fixing work completed.
Current Month	96%External Paint 1st coat work completed.
Activity	P
Up to Last Month	95%External Paint 1 <sup>st</sup> coat work completed.
Block B04	Chinaware work completed.
	Staircase railing one coat paint work completed.
	Staircase flush door fixing work completed.
	• 12 <sup>th</sup> Floor Aluminium door windows silicon filling work in progress.
	Common area light fixture fixing work completed.
Current Month	96%External Paint 1st coat work completed.
Activity	• 13th Floor Aluminium door windows silicon filling work in progress.
	• Common area shaft paint work in progress.
Up to Last Month	• 90%External Paint 1 <sup>st</sup> coat work completed.
Block B05	Flats meter board fixing work in progress.
	64/104 Chinaware fixing work completed.
	Staircase railing one coat paint work completed.
	Staircase flush door fixing work completed.
	Common area light fixture fixing work in progress.
Current Month	• 92%External Paint 1st coat work completed.
Activity	• Flats meter board fixing work in progress.
	• 88/104 Chinaware fixing work completed.
	Common area shaft paint work in progress.
Up to Last Month	• 100% First coat External Painting work completed.
Block C-16	Common area light fixture fixing work completed.
	Smoke detector fixing work in progress.
	Staircase railing one coat paint work completed.
	Staircase flush door fixing work completed.
Current Month	Smoke detector fixing work completed.
Activity	Mumty Machine room external paint work in progress.
	• Common area shaft paint work in progress.
	Meter board fixing work in progress.
	Rising main fixing work in progress.
Up to Last Month	• 100% First coat External Painting work completed.
Block C-17	Common area light fixture fixing work completed.
	Smoke detector fixing work in progress.
	Staircase railing one coat paint work completed.
	Staircase flush door fixing work in progress.





		GEWHO - GREATER NOIDA I ROJECT
Current Month	•	Smoke detector fixing work completed.
Activity	•	Staircase flush door fixing work completed.
	•	Mumty Machine room external paint work in progress.
	•	Common area shaft paint work in progress.
	•	Meter board fixing work in progress.
	•	Rising main fixing work in progress.
<b>Up to Last Month</b>	•	100% First coat External Painting work completed.
Block C-02	•	Staircase railing one coat paint work completed.
	•	Staircase flush door fixing work completed.
	•	Lift installation work completed testing work pending.
<b>Current Month</b>	•	Lift testing work in progress.
Activity	•	Meter board fixing work in progress.
	•	Rising main fixing work completed.
	•	Exhaust fan fixing work completed.
<b>Up to Last Month</b>	•	Chinaware fixing work completed.
Block C-03	•	80% First coat External Painting work completed.
	•	Staircase railing one coat paint work completed.
	•	Staircase flush door fixing work completed.
	•	Lift installation work completed testing work pending.
<b>Current Month</b>	•	85% First coat External Painting work completed.
Activity	•	Lift testing work in progress.
	•	Meter board fixing work in progress.
	•	Rising main fixing work completed.
	•	Exhaust fan fixing work completed.
<b>Up to Last Month</b>	•	90% First coat External Painting work completed.
Block C-04	•	Staircase railing one coat paint work completed.
	•	Staircase flush door fixing work completed.
	•	Lift installation work completed testing work pending.
<b>Current Month</b>	•	95% First coat External Painting work completed.
Activity	•	Lift testing work in progress.
	•	Meter board fixing work in progress.
	•	Rising main fixing work completed.





	SSE (FIE STEELING STE
<b>Up to Last Month</b>	90% STP mechanical fixing work completed.
NTA	• 97% Soil filling work in Road completed.
	• Steel binding for VDF in progress.
	• VDF casting work completed of Road. (1500 /6161.0 Sqm)
	PCC for VDF work completed. (1500 /6161.0 Sqm)
	Amphitheatre granite fixing work completed.
	Green area development work in progress.
	• 72% Kerb stone fixing work completed.
	Boundary wall first coat putty work in progress.
	• Feature wall Granite fixing work completed.
	• 95% Foot path chequered tile fixing work completed.
	Drain wall granite fixing work in progress.
	• Cut out Polycarbonate sheet and louver fixing work completed.
<b>Current Month</b>	• 95% STP mechanical fixing work completed.
Activity	• 98% Soil filling work in Road completed.
	• Steel binding for VDF in progress.
	• VDF casting work completed of Road. (5200 /6161.0 Sqm)
	PCC for VDF work completed. (5200 /6161.0 Sqm)
	Green area development work in progress.
	• 95% Green Area Kerb stone fixing work completed.
	• 30% Parking area Kerb stone fixing work completed.
	Boundary wall first coat putty work completed.
	• 98% Foot path chequered tile fixing work completed.
	Drain wall granite fixing work in progress.





# PHOTOGRAPHS OF PACKAGE-IV on 31st MAY - 2021

#### **BIRD EYE VIEW OF PROJECT**







### EXTERNAL ROAD DEVELOPMENT IS IN PROGRESS.







# BLOCK C02, C03 &C04 EXTERNAL PAINT WORK IN PROGRESS.







### GREEN AREA AND ROAD DEVELOPMENT WORK IN PROGRESS.







# **CENTER PARK DEVELOPMENT WORK IN PROGRESS.**







PACKAGE-V	STATUS AS ON 31/05/2021
Up to Last Month	
	• External painting 1 <sup>st</sup> coat work 23% completed. (Total 98%).
Block B01	<ul> <li>Main Staircase Door Shutter fixing work completed.</li> </ul>
	• Lift testing work in progress.
	• 6 <sup>th</sup> floor Aluminium door window silicon filling work in progress.
<b>Current Activity</b>	
	• Lift testing work in progress.
	• 7th floor Aluminium door window silicon filling work in progress.
	• External painting work 1 <sup>st</sup> coat 5% completed. (Total 75%).
Up to Last Month	<ul> <li>Main Staircase Door Shutter fixing work completed.</li> </ul>
D. 1 D.	<ul> <li>Aluminium door window silicon filling work in progress.</li> </ul>
Block B02	E / 1 * /* 14st / #0/ 1 / 1 //E / 1000/
Current Activity	• External painting work 1st coat 5% completed. (Total 80%).
	9 <sup>th</sup> Floor Aluminium door window silicon filling work completed.
Up to Last Month	• Internal putty work 2 <sup>nd</sup> coat competed up to 13 <sup>th</sup> floor.
DI 1 D02	• Internal door shutters fixing work 5% completed. (Total 100%).
Block B03	<ul> <li>Aluminum door window glass fixing work 95% completed.</li> </ul>
	• 7 <sup>th</sup> floor Internal painting 1 <sup>st</sup> coat completed.
	• Diverter fixing work 100% completed.
	Lift Car body and motor location work completed.
	• 100% Lift cladding work completed.
	• 70% External Painting work completed.
	• 100% tile fixing work completed.
<b>Current Activity</b>	10th @ T / 1 1 1 1 1 1 1
	• 12 <sup>th</sup> floor Internal painting 1 <sup>st</sup> coat completed.
	80% External Painting work completed.
Un to Lost Month	• 60% External Painting work completed.
Up to Last Month	Toilets Exhaust fans fixing work completed.  Week beginn fixing words a small to define the fixed for the fix
Block C15	Wash basins fixing work completed.  M. G.
DIVER C13	Main Staircase Door Shutter fixing work completed.  Life to sting any other property.
	Lift testing work in progress.  Pricing main fiving work in progress.
	Rising main fixing work in progress.  Metar board fixing work completed.
Current Activity	Meter board fixing work completed.  709/ External Pointing work completed.
Current Activity	• 70% External Painting work completed.
	Lift testing work in progress.     Dising main fixing work in progress.
	<ul> <li>Rising main fixing work in progress.</li> </ul>





	CGEWHO - GREATER NOIDAT ROSECT
<b>Up to Last Month</b>	• External painting work 1 <sup>st</sup> coat work 20% completed. (Total 90%).
	Entry door polish work completed.
	Wash basins fixing work completed.
Block C14	Toilets & Kitchen Exhaust fans fixing work completed.
	Main Staircase Door Shutter fixing work completed.
	Lift testing work in progress.
	Aluminium door window silicon filling work completed.
	Rising main fixing work in progress.
	Meter board fixing work completed.
<b>Current Activity</b>	Lift testing work in progress.
	Rising main fixing work in progress.
<b>Up to Last Month</b>	WBM Road work PCC completed (Total 98%).
	Grass Pavers fixing work near blocks completed.
	• Kerb stone and Graver Pavers Fixing work in parking in progress. (07 parking /
Non-Tower	10 parking)
	Garden hydrant piping work 4% completed. (Total 99%).
	90% Road PCC work completed.
	80% Road VDF work completed.
	Pergola Ms structure work completed.
	Granite fixing on planter and drain wall work completed.
	Green area development work in progress.
	Basement fire fighting main line connection work in progress.
<b>Current Activity</b>	• Kerb stone and Graver Pavers Fixing work in parking in progress. (08 parking / 10 parking)
	• 85% Road VDF work completed.
	Green area development work in progress.
	Basement fire fighting main line connection work in progress.
	• Near Block B01, B02 &C14 Road Grass paver fixing work completed.
	(40%)
	Wall Tile fixing work in progress around cut out bottom.
	9 1 6





# PHOTOGRAPHS OF PACKAGE-V on 31st MAY -2021


#### **BIRD EYE VIEW OF PROJECT.**







#### **CENTER PARK TOP VIEW.**







#### BLOCK B01,B02,B03 EXTRNAL PAINT WORK IN PROGRESS.







#### EXTERNAL ROAD VDF WORK IS IN PROGRESS.







### **GREEN AREA DEVELOPMENT WORK IN PROGRESS.**







PACKAGE-VI	STATUS AS ON 31/05/2021
Up to Last Month	Main Gate no-1 & 2 external wall Granite fixing work in progress.
Boundary Wall &	• Main Gate no- 1,2 &3 Door frame fixing work completed.
Gates	
Current Month	• Main Gate Main Gate no-1 & 2 external wall Granite fixing work in
Activity	progress.
	Main Gate no- 03 Brick coba work is on progress.
Up to Last Month	• One Water tank Roof slab casting work completed.
Shopping.	• 95% Internal putty work completed.
	• 95% External plaster Putty work completed.
	• 100% floor tile fixing work completed on First & Second floor.
	• 70% floor tile fixing work completed on ground floor shops.
	• Staircase Kota stone fixing work in progress.
	• SS Railing work completed in corridor on First & Second Floor.
	MS Framing work in progress of Cut Out.
	Basement C. I. work in progress.
<b>Current Month</b>	• Water tank -02 Roof slab shuttering work is on progress.
Activity	• 95% Internal putty work completed.
	• 100% External plaster Putty work completed.
	• Floor tile fixing work is on progress on ground floor shops.
	• 100% Staircase Kota stone fixing work completed.
	MS Framing work in progress of Cut Out.
	Basement C. I. work in progress.
	• Ground floor entrance Kota work is on progress.
Up to Last Month	100% Terrace projection casting work completed.
Nursing	• 100% AAC block fixing work completed on Ground, First & Second
	Floor.
	Mumty slab casting work completed.
	• 100% Internal plaster completed.
	• 90% External plaster & Putty work completed.
	CPVC fixing work in progress.
Current Month	
Activity	• Remaining 10% External plaster & Putty work completed.
·	• CPVC fixing work in progress.
	Staircase Kota work in progress.
	• 75% Internal putty work completed.
	Water tank base slab reinforcement work is on progress.
Up to Last Month	First floor columns casting work completed.
School	• First Floor slab casting work completed.
Current Month	Stub column casting work is on progress.
Activity	<ul> <li>Ground floor ACC block layout work is on progress.</li> </ul>
= = = 3 J	Ground moor recommendation in progress.





CGE	TVIIO GREITER TOIDITI ROUECT
Up to Last Month	• 100% First floor Roof slab casted.
<b>Community Center</b>	• 100% Second floor casting work completed.
	• 90% Third floor column casting work completed.
	• Third floor slab shuttering and reinforcement work in progress.
	• 50% Ground floor ACC Block fixing work completed.
Current Month	To the street and the street and
Activity	• Remaining 10% Third floor column casting work completed.
11001/10	• 40% Third floor slab casted & remaining slab shuttering &
	reinforcement work is on progress.
	• 40% terrace floor column reinforcement work completed.
	• 20% Ground floor ACC Block fixing work completed.
Up to Last Month	100% Kota stone waterproofing on Retaining wall completed.
Non-Tower Area	<ul> <li>80% Basement VDF flooring completed.</li> </ul>
	• 30% APP membrane water proofing work completed.
	• 30% Screeding on water proofing membrane completed.
	<ul> <li>MS framing fixing work in progress. (2/8) cut out.</li> </ul>
	<ul> <li>Harvesting brick work in progress. (1/2).</li> </ul>
	<ul> <li>Basement fire fighting work in progress.</li> </ul>
	<ul> <li>Basement putty work in progress.</li> </ul>
	<ul> <li>Kerb stone fixing work in progress.</li> </ul>
	There stone fixing work in progress.
Current Month	
Activity	• 90% Basement VDF flooring completed.
,	• 40% APP membrane water proofing work completed.
	• 10% Screeding on water proofing membrane completed.
	• MS framing fixing work in progress. (3/8) cut out.
	• Harvesting brick work completed (2/2).
	<ul> <li>Basement fire fighting work in progress.</li> </ul>
	<ul> <li>Kerb stone fixing work in progress.</li> </ul>
	<ul> <li>Sewer manhole B/W is on progress.</li> </ul>
	• 90% Basement plaster work completed.
	• 20% Basement putty work completed.





# PHOTOGRAPHS OF PACKAGE-VI on 31st MAY - 2021

#### **OVERALL VIEW OF PACKAGE VI**







# SHOPPING AREA EXTERNAL PUTTY & NTA WATER PROOFING WORK IN PROGRESS.







# COUMNITY HALL SECOND FLOOR ROOF SLAB SHUTTERING WORK IN PROGRESS.







#### **GATE NO.-2**







## **QUALITY CONTROL**

# <u>DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS</u> <u>CONDUCTED AT SITE:</u>

S. No.	Materials	Source From	Test Date	Tests done	Result
1	Coarse Sand	Bajpur		Each truck	Sieve Analysis & Silt content
2	Coarse Aggregate	Nangal		Each truck	Sieve Analysis & Impact Value
3	Fine Sand	Yamuna Nagar		Each truck	Sieve Analysis & Silt content
4	Bricks	Greater Noida		Each truck	Dimension, Water Absorption & Compressive strength
5	Cement	Third party testing is being done			
6	Steel	Third party testing is being done			
7	Piles Integrity	Third party testing is being done			
8	Soil Compaction		Third party te	esting is being done	
9	STP water	Third party testing is being done			
10	Wood	Third party testing is being done			
11	Wires	Third party testing is being done			
12	Tiles	Third party testing is being done			
13	VDF	Third party testing is being done (Flexural Strength done.).			
14	RCC Cubes are being tested and Register is being maintained.				
15	Slump test conducted at site to insure workability if concrete.				





#### **BRICKS COMPRESSIVE STRENGTH TESTING**







## **CUBE COMPRESSIVE STRENGTH TESTING**







#### **COARSE AGGREGATE 20MM TESTING**







#### **COARSE SAND SIEVIE ANALASYS TESTING.**







PACKAGE-E (a)	STATUS AS ON 31/05/2021	
Up to Last Month	• Substation -3, 5A, 4 Brick work 100% completed.	
	DG set foundation 70% completed.	
	• ESS-3, 5A Transformer installing work completed.	
	ESS-3 LT room cable tray work in progress.	
	DG set installing work in progress. (2/6) Nos.	
	6mtrs pole fixing work is in progress. (24/68) Nos.	
	• 3mtrs pole fixing work is in progress. (23/176) Nos.	
	Cable laying with GI wire work in progress for lights.	
	33/11kv substation Transformer foundation work completed.	
	33/11Kv substation panel room slab shuttering and steel binding work in	
	progress.	
	Main meter/receiver room foundation work completed and brick work in	
	progress.	
	Chemical & Plate earthing work is in progress.	
	Substation earthing work in progress.	
Current Month	DC set foundation 1000/ completed	
Activity	• DG set foundation 100% completed.	
Activity	<ul> <li>ESS-3 LT room cable tray work completed.</li> <li>DG set installing work in progress. (4/6) Nos.</li> </ul>	
	<ul> <li>DG set installing work in progress. (4/6) Nos.</li> <li>6mtrs pole fixing work is in progress. (40/68) Nos.</li> </ul>	
	<ul> <li>3mtrs pole fixing work is in progress. (40/00) Nos.</li> <li>3mtrs pole fixing work is in progress. (35/176) Nos.</li> </ul>	
	<ul> <li>Cable laying with GI wire work in progress for lights.</li> </ul>	
	<ul> <li>33/11Kv substation panel room slab casting work completed.</li> </ul>	
	• 33/11Kv substation panel room slab casting work completed. • 33/11Kv substation boundary wall excavation work completed.	
	• 33/11Kv substation boundary wan excavation work completed.	
	<ul> <li>Main meter/receiver room slab casting work completed.</li> </ul>	
	<ul> <li>Chemical &amp; Plate earthing work is in progress. (32/40)</li> </ul>	
	<ul> <li>Substation earthing work in progress. (32/40)</li> </ul>	
	- Substation carting work in progress. (30/40)	





## TRANSFORMER INSTALASTION WORK IN PROGRESS.







#### **D.G SET INSTALASTION WORK IN PROGRESS.**







PACKAGE-E (b)	STATUS AS ON 31/05/2021
Up to Last Month	<ul> <li>DG foundation at Substation -1, 2 &amp; 5b completed.</li> <li>ESS-1 DG set installing work completed. (2/6) Nos.</li> <li>ESS-1, 2 &amp; 5b Transformer installing work completed.</li> <li>ESS-2 earthing work in progress. (14/28) Nos.</li> <li>3mtrs pole fixing work is in progress. (30/65) Nos.</li> <li>90% Basement cable tray work completed.</li> <li>Chemical &amp; Plate earthing work is in progress.</li> </ul>
Current Month Activity	<ul> <li>ESS-1 DG set installing work completed. (4/6) Nos.</li> <li>ESS-2 earthing work in progress. (18/28) Nos.</li> <li>3mtrs pole fixing work is in progress. (30/65) Nos.</li> <li>95% Basement cable tray work completed.</li> <li>Chemical &amp; Plate earthing work is in progress.</li> <li>LT Panel installation work in progress.</li> </ul>





#### TRANSFORMER INSTALASTION WORK IN PROGRESS.







#### **D.G. SET INSTALASTION WORK IN PROGRESS**





