


PROGRESS OF CONSTRUCTION OF TOWERS Phase-II Housing Project, Mohali													AS ON	30.09.2015			
Sr. No.	Activities	TW-XIII A2	TW-XV B5	TW-XI B6	TW-XII B7	TW-XVI C4	TW-XIV C5	TW-XVII D3	TW-XVIII D4	Community Centre	Guard Room 1&2	Covd. Car Parking	Remarks				
1	Excavation in foundation	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	90%	UGT & PUMP Room RCC completed				
2	P.C.C. in foundation	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	90%	Sewerage & Storm line in progress & HT Room Internal & External Plaster Completed				
3	R.C.C. in raft foundation/Footing	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	90%	Lift Work in progress Block C5&B5 & Harvesting Pit work in progress				
4	R.C.C. in column upto Plinth Level	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	90%	ATT in Progress C5 Block				
5	R.C.C. in Plinth Beam	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	90%					
6	RCC Column and slab																
(i)	Ground Floor column	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	87%					
	Ground Floor slab	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	54%					
(ii)	First floor column	100%	100%	100%	100%	100%	100%	100%	100%	100%	X	X					
	First floor slab	100%	100%	100%	100%	100%	100%	100%	100%	100%	X	X					
(iii)	Second floor column	100%	100%	100%	100%	100%	100%	100%	100%	100%	X	X					
	Second floor slab	100%	100%	100%	100%	100%	100%	100%	100%	100%	X	X					
(iv)	Third floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Third floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(v)	Fourth floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Fourth floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(vi)	Fifth floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Fifth floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(vii)	Sixth floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Sixth floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(viii)	Seventh floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Seventh floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(ix)	Eighth floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Eighth floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(x)	Ninth floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Ninth floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(xi)	Tenth floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Tenth floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(xii)	Eleventh floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Eleventh floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(xiii)	Twelfth floor column	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
	Twelfth floor slab	100%	100%	100%	100%	100%	100%	100%	100%	X	X	X					
(xiv)	Thirteenth floor column	X	100%	X	100%	100%	100%	X	X	X	X	X					
	Thirteenth floor slab	X	100%	X	100%	100%	100%	X	X	X	X	X					
	Mumty, Machine room, OHT	100%	100%	100%	100%	100%	100%	100%	100%	100%	X	X					
7	Brick Work in Super Structure																
(i)	Brick work & lintels G.Floor	90%	95%	95%	80%	90%	100%	90%	80%	95%	100%	29%					
(ii)	Brick work & lintels 1st Floor	95%	95%	95%	95%	95%	100%	95%	95%	95%							
(iii)	Brick work and lintels 2nd Floor	95%	95%	95%	95%	95%	100%	95%	95%	95%							
(iv)	Brick work and lintels 3rd Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(v)	Brick work and lintels 4th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(vi)	Brick work and lintels 5th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(vii)	Brick work and lintels 6th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(viii)	Brick work and lintels 7th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(ix)	Brick work and lintels 8th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(x)	Brick work and lintels 9th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(xi)	Brick work and lintels 10th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(xii)	Brick work and lintels 11th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(xiii)	Brick work and lintels 12th Floor	95%	95%	95%	95%	95%	100%	95%	95%								
(xiv)	Brick work and lintels 13th Floor	X	95%	X	95%	95%	100%	X	X								


For Kanwarji Const. Co.


Auth. Signature

[Handwritten signatures and initials]
 J.E. (C)
 J.E. (C)
 J.E. (C)
 J.E. (C)

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community	Guard	Covd. Car Parking	Remarks
No.	Activities	A2	B5	B6	B7	C4	C5	D3	D4	Centre	Room 1&2		
8	Internal Wall Conduit												
(i)	Ground Floor Internal Wall conduit	75%	80%	-	40%	34%	100%	80%	17%	100%	100%		
(ii)	Ist floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%		
(iii)	IInd floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%		
(iv)	IIIrd floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%		
(v)	IVth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(vi)	Vth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(vii)	VIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(viii)	VIIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(ix)	VIIIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(x)	IXth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(xi)	Xth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(xii)	XIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(xiii)	XIIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(xiv)	XIIIth floor Internal Wall conduit	X	100%	X	100%	100%	100%	X	X	-	-		
9	Internal G.I.												
(i)	Ground Floor Internal G.I.	50%	20%	20%	-	34%	100%	-	-	-	-		
(ii)	Ist floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(iii)	IInd floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	50%	-		
(iv)	IIIrd floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(v)	IVth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(vi)	Vth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(vii)	VIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(viii)	VIIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(ix)	VIIIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(x)	IXth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(xi)	Xth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(xii)	XIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(xiii)	XIIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	-	-		
(xiv)	XIIIth floor Internal G.I.	X	100%	X	100%	100%	100%	X	X	-	-		
10	Vertical G.I. shaft												
(i)	Ground Floor Vertical G.I. shaft	-	-	-	-	-	-	-	-	33%	-		
(ii)	Ist floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	33%	-		
(iii)	IInd floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	33%	-		
(iv)	IIIrd floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(v)	IVth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(vi)	Vth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(vii)	VIth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(viii)	VIIth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(ix)	VIIIth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(x)	IXth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(xi)	Xth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(xii)	XIth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(xiii)	XIIth floor Vertical G.I. shaft	95%	100%	100%	100%	100%	100%	66%	95%	-	-		
(xiv)	XIIIth floor Vertical G.I. shaft	X	100%	X	100%	100%	100%	X	X	-	-		


 JE (C)


 JE (C)


 For C.M. S.P. & M.

For Kanwarji Const. Co.


 Auth. Signatory

Sr. No.	Activities	TW-XIII A2	TW-XV B5	TW-XI B6	TW-XII B7	TW-XVI C4	TW-XIV C5	TW-XVII D3	TW-XVIII D4	Community Centre	Guard Room 1&2	Remarks
11	Internal C.I. & vertical C.I.											
(i)	Ground Floor Internal C.I. & vertical C.I.	-	-	-	-	-	-	-	-	33%		Only vertical C.I./CC
(ii)	Ist floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	33%		Only vertical C.I./CC
(iii)	IInd floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	33%		Only vertical C.I./CC
(iv)	IIIrd floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(v)	IVth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(vi)	Vth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(vii)	VIth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(viii)	VIIth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(ix)	VIIIth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(x)	IXth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(xi)	Xth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(xii)	XIth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(xiii)	XIIth floor Internal C.I. & vertical C.I.	50%	100%	100%	100%	100%	100%	95%	95%	-		
(xiv)	XIIIth floor Internal C.I. & vertical C.I.	-	100%	X	100%	100%	100%	X	X	-		
12	Rain Water Pipe											
(i)	Ground Floor Vertical RWP	-	95%	-	-	17%	95%	-	-	25%		
(ii)	Ist Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%	25%		
(iii)	IInd Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%	25%		
(iv)	IIIrd Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(v)	IVth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(vi)	Vth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(vii)	VIth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(viii)	VIIth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(ix)	VIIIth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(x)	IXth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(xi)	Xth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(xii)	XIth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(xiii)	XIIth Floor Vertical RWP	75%	100%	100%	100%	100%	100%	100%	100%			
(xiv)	XIIIth Floor Vertical RWP	X	100%	X	100%	100%	100%	X	X			
13	Wooden Door frame fixing											
(i)	Door frames G floor	-	35%	-	-	-	60%	50%	60%	-	100%	
(ii)	Door frames Ist floor wooden	100%	100%	100%	100%	100%	100%	100%	100%	-		
(iii)	Door frames IInd floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(iv)	Door frames IIIrd floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(v)	Door frames IVth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(vi)	Door frames Vth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(vii)	Door frames VIth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(viii)	Door frames VIIth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(ix)	Door frames VIIIth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(x)	Door frames IXth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(xi)	Door frames Xth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(xii)	Door frames XIth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(xiii)	Door frames XIIth floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(xiv)	Door frames XIIIth floor	X	100%	X	100%	100%	100%	X	X	-		
14	Internal Plaster											
(i)	Ground Floor Internal Plaster	-	-	-	-	-	-	-	-	-		
(ii)	Ist floor Internal Plaster	15%	95%	95%	95%	95%	95%	95%	95%	-	95%	28%
(iii)	IInd floor Internal Plaster	90%	95%	95%	95%	95%	95%	95%	95%	-		
(iv)	IIIrd floor Internal Plaster	90%	95%	95%	95%	95%	95%	95%	95%	-		

For Kanwari Const. Co.

J.E. (W)

J.E. (S)

*Kanwar Kumar
for CM Section & Ass.*

[Signature]
Auth. Signatory

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community Centre	Guard Room 1&2	Covd. Car Parking	Remarks
No.	Activities	A2	B5	B6	B7	C4	C5	D3	D4				
(v)	IVth floor Internal Plaster	95%	95%	95%	95%	95%	95%	95%	95%	-			
(vi)	Vth floor Internal Plaster	95%	95%	95%	95%	95%	95%	95%	95%	-			
(vii)	Vth floor Internal Plaster	95%	95%	95%	95%	95%	95%	95%	95%	-			
(viii)	VIIth floor Internal Plaster	20%	95%	95%	95%	95%	95%	95%	95%	-			
(ix)	VIIIth floor Internal Plaster	-	95%	95%	95%	95%	95%	95%	95%	-			
(x)	IXth floor Internal Plaster	-	95%	95%	95%	95%	95%	95%	95%	-			
(xi)	Xth floor Internal Plaster	-	95%	95%	95%	95%	95%	95%	95%	-			
(xii)	XIth floor Internal Plaster	-	95%	95%	95%	95%	95%	95%	95%	-			
(xiii)	XIIth floor Internal Plaster	-	95%	95%	95%	95%	95%	95%	95%	-			
(xiv)	XIIIth floor Internal Plaster	-	95%	X	95%	95%	95%	-	-	-			
15	D.B. Fixing												
(i)	Ground Floor D.B. Fixing	-	-	-	-	-	-	-	-	100%	100%		
(ii)	Ist Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	100%			
(iii)	IInd Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	100%			
(iv)	IIIrd Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(v)	IVth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(vi)	Vth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(vii)	VIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(viii)	VIIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(ix)	VIIIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(x)	IXth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(xi)	Xth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(xii)	XIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(xiii)	XIIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(xiv)	XIIIth Floor D.B. Fixing	X	100%	X	100%	100%	100%	X	X	-			
16	A.C.Box Fixing												
(i)	Ground floor A.C. box fixing	-	-	-	-	-	-	-	-	100%			
(ii)	Ist Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	100%			
(iii)	IInd Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	100%			
(iv)	IIIrd Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(v)	IVth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(vi)	Vth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(vii)	VIth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(viii)	VIIth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(ix)	VIIIth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(x)	IXth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(xi)	Xth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(xii)	XIth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(xiii)	XIIth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	-			
(xiv)	XIIIth Floor A.C. box Fixing	X	100%	X	100%	100%	100%	X	X	-			
17	MS Railing for Balcony & stair case												
(i)	MS Railing for Balcony & stair case G Floor	-	-	-	-	-	-	-	-	-			
(ii)	MS Railing for Balcony & stair case Ist Floor	100%	100%	100%	100%	100%	100%	100%	100%	-			
(iii)	MS Railing for Balcony & stair case IInd Floor	100%	100%	100%	100%	100%	100%	100%	100%	-			
(iv)	MS Railing for Balcony & stair case IIIrd Floor	100%	100%	100%	100%	100%	100%	100%	100%	-			
(v)	MS Railing for Balcony & stair case IVth Floor	100%	100%	100%	100%	100%	100%	100%	100%	-			
(vi)	MS Railing for Balcony & stair case Vth Floor	100%	100%	100%	100%	100%	100%	100%	100%	-			
(vii)	MS Railing for Balcony & stair case VIth Floor	100%	100%	100%	100%	100%	100%	100%	100%	-			
(viii)	MS Railing for Balcony & stair case VIIth Floor	100%	100%	100%	100%	100%	100%	100%	100%	-			
(ix)	MS Railing for Balcony & stair case VIIIth Floor	100%	100%	100%	100%	100%	100%	100%	100%	-			

For Kanwarji Const. Co.

gsk
JE(C)

AB
JE(C)

Pawan Pawan
For CM Refractor Ass.

[Signature]
Auth. Signatory

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community Centre	Guard Room 1&2	Covd. Car Parking	Remarks
No.	Activities	A2	B5	B6	B7	C4	C5	D3	D4				
(x)	MS Railing for Balcony & stair case IXth Floor	100%	100%	100%	100%	100%	100%	100%	100%				
(xi)	MS Railing for Balcony & stair case Xth Floor	100%	100%	100%	100%	100%	100%	100%	100%				
(xii)	MS Railing for Balcony & stair case XIth Floor	100%	100%	100%	100%	100%	100%	100%	100%				
(xiii)	MS Railing for Balcony & stair case XIIth Floor	100%	100%	100%	100%	100%	100%	100%	100%				
(xiv)	MS Railing for Balcony & stair case XIIIth Floor	X	100%	X	100%	100%	100%	X	X				
18	Sunken Water Proofing												
(i)	Sunken Water Proofing 1st Floor	15%	100%	100%	60%	100%	100%	15%	67%				
(ii)	Sunken Water Proofing 2nd Floor	-	100%	100%	100%	100%	100%	42%	67%				
(iii)	Sunken Water Proofing 3rd Floor	-	100%	100%	100%	100%	100%	42%	67%				
(iv)	Sunken Water Proofing 4th Floor	-	100%	100%	100%	100%	100%	42%	67%				
(v)	Sunken Water Proofing 5th Floor	-	100%	100%	100%	100%	100%	42%	67%				
(vi)	Sunken Water Proofing 6th Floor	-	100%	100%	100%	100%	100%	42%	67%				
(vii)	Sunken Water Proofing 7th Floor	-	100%	100%	100%	100%	100%	42%	67%				
(viii)	Sunken Water Proofing 8th Floor	-	100%	100%	100%	100%	100%	42%	67%				
(ix)	Sunken Water Proofing 9th Floor	-	100%	100%	100%	100%	100%	42%	67%				
(x)	Sunken Water Proofing 10th Floor	-	100%	100%	100%	100%	100%	42%	34%				
(xi)	Sunken Water Proofing 11th Floor	-	100%	100%	100%	100%	100%	-	34%				
(xii)	Sunken Water Proofing 12th Floor	-	100%	100%	100%	100%	100%	-	50%				
(xiii)	Sunken Water Proofing 13th Floor	-	100%	X	100%	100%	100%	X	X				
19	Glazed Tiles Fixing												
(i)	Glazed Tiles Fixing Ground Floor	-	-	-	-	-	-	-	-				
(ii)	Glazed Tiles Fixing 1st Floor	15%	100%	95%	85%	67%	100%	35%	-				
(iii)	Glazed Tiles Fixing 2nd Floor	-	100%	95%	95%	95%	100%	35%	40%				
(iv)	Glazed Tiles Fixing 3rd Floor	-	100%	95%	95%	95%	100%	35%	40%				
(v)	Glazed Tiles Fixing 4th Floor	-	100%	95%	95%	95%	95%	35%	40%				
(vi)	Glazed Tiles Fixing 5th Floor	-	100%	95%	95%	95%	95%	35%	40%				
(vii)	Glazed Tiles Fixing 6th Floor	-	100%	95%	95%	95%	95%	35%	40%				
(viii)	Glazed Tiles Fixing 7th Floor	-	100%	95%	95%	95%	95%	35%	40%				
(ix)	Glazed Tiles Fixing 8th Floor	-	100%	95%	95%	95%	95%	35%	40%				
(x)	Glazed Tiles Fixing 9th Floor	-	100%	95%	95%	95%	95%	35%	40%				
(xi)	Glazed Tiles Fixing 10th Floor	-	100%	95%	95%	95%	95%	35%	40%				
(xii)	Glazed Tiles Fixing 11th Floor	-	100%	95%	95%	95%	95%	-	40%				
(xiii)	Glazed Tiles Fixing 12th Floor	-	100%	95%	95%	95%	95%	-	-				
(xiv)	Glazed Tiles Fixing 13th Floor	-	100%	-	95%	95%	95%	-	-				
20	Kota Stone Fixing												
(i)	Kota Stone Fixing Ground Floor	-	-	-	-	-	-	-	-				
(ii)	Kota Stone Fixing 1st Floor	-	95%	95%	95%	95%	95%	-	-				
(iii)	Kota Stone Fixing 2nd Floor	-	95%	95%	95%	95%	95%	-	-				
(iv)	Kota Stone Fixing 3rd Floor	-	95%	95%	95%	95%	95%	-	-				
(v)	Kota Stone Fixing 4th Floor	-	95%	95%	95%	95%	95%	-	-				
(vi)	Kota Stone Fixing 5th Floor	-	95%	95%	95%	95%	95%	-	-				
(vii)	Kota Stone Fixing 6th Floor	-	95%	95%	95%	95%	95%	-	-				
(viii)	Kota Stone Fixing 7th Floor	-	95%	95%	95%	95%	95%	-	-				
(ix)	Kota Stone Fixing 8th Floor	-	95%	95%	95%	95%	95%	90%	-				
(x)	Kota Stone Fixing 9th Floor	-	95%	95%	95%	95%	95%	90%	-				
(xi)	Kota Stone Fixing 10th Floor	-	95%	95%	95%	95%	95%	90%	-				
(xii)	Kota Stone Fixing 11th Floor	-	95%	95%	95%	95%	95%	90%	-				

For Kanwalji Const. Co

J.E (C)
J.E (E)
For Const. Co. Ass.

[Signature]
 Auth. Signator

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community	Guard		Remarks
No.	Activities	A2	B5	B6	B7	C4	C5	D3	D4	Centre	Room 1&2	Covd. Car Parking	
(xiii)	Kota Stone Fixing 12th Floor	-	95%	95%	95%	95%	95%	90%	-	-			
(xiv)	Kota Stone Fixing 13th Floor	-	95%	-	95%	95%	95%	-	-	-			
21	Kitchen Counter Fixing												
(i)	Kitchen Counter Fixing Ground Floor	-	-	-	-	-	-	-	-	-			
(ii)	Kitchen Counter Fixing 1st Floor	15%	95%	95%	95%	95%	95%	95%	-	-			
(iii)	Kitchen Counter Fixing 2nd Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(iv)	Kitchen Counter Fixing 3rd Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(v)	Kitchen Counter Fixing 4th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(vi)	Kitchen Counter Fixing 5th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(vii)	Kitchen Counter Fixing 6th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(viii)	Kitchen Counter Fixing 7th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(ix)	Kitchen Counter Fixing 8th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(x)	Kitchen Counter Fixing 9th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(xi)	Kitchen Counter Fixing 10th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(xii)	Kitchen Counter Fixing 11th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(xiii)	Kitchen Counter Fixing 12th Floor	-	95%	95%	95%	95%	95%	95%	-	-			
(xiv)	Kitchen Counter Fixing 13th Floor	-	95%	-	95%	95%	95%	95%	-	-			
22	Vetrified/Ceramic Tile Fixing												
(i)	vetrified/ceramic tile Fixing Ground Floor	-	-	-	-	-	-	-	-	-			
(ii)	vetrified/ceramic tile Fixing 1st Floor	15%	40%	-	-	15%	80%	15%	-	-			
(iii)	vetrified/ceramic tile Fixing 2nd Floor	-	90%	80%	80%	80%	100%	-	-	-			
(iv)	vetrified/ceramic tile Fixing 3rd Floor	-	90%	80%	80%	80%	100%	-	-	-			
(v)	vetrified/ceramic tile Fixing 4th Floor	-	90%	80%	80%	80%	100%	-	-	-			
(vi)	vetrified/ceramic tile Fixing 5th Floor	-	90%	80%	80%	80%	100%	-	-	-			
(vii)	vetrified/ceramic tile Fixing 6th Floor	-	90%	60%	60%	60%	80%	-	-	-			
(viii)	vetrified/ceramic tile Fixing 7th Floor	-	90%	80%	80%	80%	100%	-	-	-			
(ix)	vetrified/ceramic tile Fixing 8th Floor	-	90%	80%	80%	80%	100%	-	-	-			
(x)	vetrified/ceramic tile Fixing 9th Floor	-	90%	80%	80%	80%	100%	-	-	-			
(xi)	vetrified/ceramic tile Fixing 10th Floor	-	90%	80%	80%	80%	100%	-	-	-			
(xii)	vetrified/ceramic tile Fixing 11th Floor	-	90%	75%	90%	90%	100%	-	-	-			
(xiii)	vetrified/ceramic tile Fixing 12th Floor	-	90%	75%	90%	90%	100%	-	-	-			
(xiv)	vetrified/ceramic tile Fixing 13th Floor	-	90%	-	90%	90%	100%	-	-	-			
23	Flush Door Fixing & Security Door												
(i)	Flush Door Fixing Ground Floor	-	-	-	-	-	-	-	-	-			
(ii)	Flush Door Fixing 1st Floor	15%	15%	-	-	15%	80%	15%	-	-			
(iii)	Flush Door Fixing 2nd Floor	-	95%	-	-	15%	95%	-	-	-			
(iv)	Flush Door Fixing 3rd Floor	-	95%	-	-	15%	95%	-	-	-			
(v)	Flush Door Fixing 4th Floor	-	95%	-	-	15%	95%	-	-	-			
(vi)	Flush Door Fixing 5th Floor	-	95%	-	-	80%	95%	-	-	-			
(vii)	Flush Door Fixing 6th Floor	-	80%	-	-	50%	95%	-	-	-			
(viii)	Flush Door Fixing 7th Floor	-	95%	-	-	15%	95%	-	-	-			
(ix)	Flush Door Fixing 8th Floor	-	95%	-	-	15%	95%	-	-	-			
(x)	Flush Door Fixing 9th Floor	-	95%	-	-	15%	95%	-	-	-			
(xi)	Flush Door Fixing 10th Floor	-	95%	-	-	-	95%	-	-	-			
(xii)	Flush Door Fixing 11th Floor	-	95%	-	-	-	95%	-	-	-			
(xiii)	Flush Door Fixing 12th Floor	-	95%	-	-	-	95%	-	-	-			
(xiv)	Flush Door Fixing 13th Floor	-	95%	-	-	-	95%	-	-	-			

[Signature]
J.E (C)

[Signature]
J.E (C)

[Signature]
For Const. Ass

For Kanwarji Const. Co.

[Signature]
Auth. Signatory

Sr. No.	Activities	TW-XIII A2	TW-XV B5	TW-XI B6	TW-XII B7	TW-XVI C4	TW-XIV C5	TW-XVII D3	TW-XVIII D4	Community Centre	Guard Room 1&2	Covd. Car Parking	Remarks
24	Aluminium window Fixing												
(i)	Aluminium Window Fixing Ground Floor	-	-	-	-	-	-	-	-	-	-	-	
(ii)	Aluminium Window Fixing 1st Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(iii)	Aluminium Window Fixing 2nd Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(iv)	Aluminium Window Fixing 3rd Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(v)	Aluminium Window Fixing 4th Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(vi)	Aluminium Window Fixing 5th Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(vii)	Aluminium Window Fixing 6th Floor	-	95%	85%	-	85%	95%	-	-	-	-	-	
(viii)	Aluminium Window Fixing 7th Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(ix)	Aluminium Window Fixing 8th Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(x)	Aluminium Window Fixing 9th Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(xi)	Aluminium Window Fixing 10th Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(xii)	Aluminium Window Fixing 11th Floor	-	95%	95%	-	95%	95%	-	-	-	-	-	
(xiii)	Aluminium Window Fixing 12th Floor	-	95%	95%	-	85%	95%	-	-	-	-	-	
(xiv)	Aluminium Window Flush Fixing 13th Floor	-	95%	X	-	85%	95%	-	-	-	-	-	
	Internal Painting including Wall Putty .OBD & Enamel Paint												
25	Internal Painting including Wall Putty.OBD&Enamel Paint												
(i)	Internal Painting including Wall Putty.OBD&Enamel Paint Ground Floor	-	-	-	-	-	-	-	-	-	-	-	
(ii)	Internal Painting including Wall Putty.OBD & Enamel Paint 1st Floor	-	-	-	-	-	60%	-	-	-	-	-	
(iii)	Internal Painting including Wall Putty.OBD & Enamel Paint 2nd Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(iv)	Internal Painting including Wall Putty.OBD & Enamel Paint 3rd Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(v)	Internal Painting including Wall Putty.OBD & Enamel Paint 4th Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(vi)	Internal Painting including Wall Putty.OBD & Enamel Paint 5th Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(vii)	Internal Painting including Wall Putty.OBD & Enamel Paint 6th Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(viii)	Internal Painting including Wall Putty.OBD & Enamel Paint 7th Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(ix)	Internal Painting including Wall Putty.OBD & Enamel Paint 8th Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(x)	Internal Painting including Wall Putty.OBD & Enamel Paint 9th Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(xi)	Internal Painting including Wall Putty.OBD & Enamel Paint 10th Floor	-	75%	-	-	-	75%	-	-	-	-	-	
(xii)	Internal Painting including Wall Putty.OBD & Enamel Paint 11th Floor	-	75%	-	-	30%	75%	-	-	-	-	-	
(xiii)	Internal Painting including Wall Putty.OBD & Enamel Paint 12th Floor	-	75%	-	-	35%	75%	-	-	-	-	-	
(xiv)	Internal Painting including Wall Putty.OBD & Enamel Paint 13th Floor	-	75%	-	-	35%	75%	-	-	-	-	-	
26	Brick Bat Koba At Terrace	-	95%	-	85%	75%	95%	-	70%	-	-	-	
27	External Plaster	-	90%	80%	80%	90%	90%	25%	-	10%	95%	28%	
Note	Out of 615 DUs slabs of 615DUs cast.												

gib
JE(C)

JE(CE)

For CM signed Ass

For Kanwar Const. Co.
Auth. Signatory