31st AUG-2017

PACKAGE-II	STATUS AS ON 31/08/2017
Up to Last Month	• 100% 3 rd floor Roof slab casting completed.
Block D03	• 26 columns casted at 4 th floor level.
Current Month Activity	 Balance 44 columns casted up to soffit of 4TH floor Roof beams.(100% columns casted) 100% 4th & 5th floor Roof slab casting done. 100% columns casted at 6th floor level.
	 Two flats Shuttering and Reinforcement binding of 6th floor Roof in progress.
	 80% Brick work in Stilt floor completed. 100% Brick work in 1st floor completed.
	 90% Brick work in 2nd floor level completed.
	• 75% Brick work in 3 rd floor level completed.
Up to Last Month	• 10% Brick work in 4 th floor level completed.
Block D04	 50% Stilt Roof slab casting completed. Shuttering and Reinforcement binding for two flats is in progress. Total 22 Columns casted at 1st floor level.
Current Month Activity	 Balance 50 % Stilt Roof Slab casted.(100% stilt roof casted) Balance 48 columns casted up to soffit of 1st floor Roof beams.(100% columns casted) 100% 1st floor Roof slab casted. 100% 2nd floor columns casted 75% 2nd floor Roof slab casted.
Up to Last Month	25% basement Roof slab casted
Block D05	 Both the staircases casted up to Basement Roof slab.
Current Month Activity	 Balance 75% basement Roof slab casted. (100% basement casted). 100% columns casted up to Soffit of Stilt Roof beam bottom. 50% Stilt Roof slab casted. Shuttering and Reinforcement binding for two flats is in progress.
Up to Last Month Block D06	 Total 70 columns casted up to soffit of basement roof beam bottom. Single flight of both the staircases shuttering & Reinforcement work completed.
Current Month Activity	• 25% Basement Roof slab casted.





Up to Last Month Block D07	• Total 49 Columns 2nd lift casted and 21 columns casted up to soffit of Basement Roof beams.			
Current Month Activity	• Balance 21 Columns casted in 2nd lift. (100% columns casted upto basement roof soffit)			
Up to Last Month Block D08	• Total 51 columns casted in 1 st lift and 40 columns casted in 2 nd lift in Basement floor.			
Current Month Activity	 Balance 19 columns casted in 1st lift and 30 columns casted in 2nd lift in Basement floor. (100% columns casted upto basement roof soffit) 			
Up to Last Month Non Tower	 Total 593 nos. of piles casted out of 593 nos. 25.57% P.C.C. for foundation work completed. 14% of Stitch slab casted. 18 Pile caps casted. Total 20 Columns casted up to soffit of Basement Roof beam bottom. Total 270 Sqm Basement Roof slab casting done. 			
Current Month Activity	 P. C. C. 5% laid(30.00% completed) Total 21 Pile caps casted. Basement Roof slab shuttering work in progress. 			
Up to Last Month Retaining Wall	 Total 72 nos. of piles casted out of 72 nos. Retaining wall footing of length 40 mtrs. Retaining wall of length 40 mtrs casted. 			
Current Month Activity	 Retaining wall of length 16mtrs casted (1st lift). Kota stone cladding (water proofing) on outer side wall is in Progress. 			
Sample Flat	 Internal Electrical conduiting & G.I. boxes completed Internal water supply piping work completed Internal soil & waste piping work Completed Internal Wooden door frames fixed R.C.C. for balcony walls casted. 70% Plaster work completed. 			





PHOTOGRAPHS OF PACKAGE-II on 31st AUGUST-2017

IN BLOCK D-04 COLUMNS CASTING AT 3RD FLR LVL IN PROGRESS.







IN BLOCK D03 6^{TH} FLR ROOF SLAB SHUTTERING WORK OF **BALANCE TWO FLATS IN PROGRESS.**







IN BLOCK D-05 STILT ROOF SLAB BALANCE TWO FLATS REINFORCEMENT BINDING WORK IN PROGRESS.







IN BLOCK D-06 BASEMENT ROOF SLAB $2^{\rm ND}$ FLAT SHUTTERING WORK IN PROGRESS.IN BLOCKS D-07 & D08 BASEMENT COLUMNS 100% COMPLETED.







IN D-TYPE SAMPLE FLAT PLASTER EXCEPT TOILET AND BALCONY COMPLETED.







IN D-TYPE SAMPLE FLAT CPVC INTERNAL WATER SUPPLY PRESSURE TESTING IN PROGRESS.







PACKAGE-III	STATUS AS ON 31/08/2017
Up to Last Month	Layout work completed.
Block C06	
Current Month Activity	• 53 nos. of piles completed out of 195 no's.
Up to Last Month	Initial testing of pile completed successfully.
Block C07	
Current Month Activity	• 72 nos. of piles completed out of 195 no's.
Up to Last Month Block C08	Excavation work 100% done.
Current Month	Layout of piles completed.
Activity	• 115 nos. of piles completed out of 195 no's.
Up to Last Month Block C01	Excavation work 100% done.
Current Month Activity	Initial testing of pile completed successfully.
Up to Last Month	Excavation work 100% done.
Block C02	
Current Month Activity	No work.





PHOTOGRAPHS OF PACKAGE-III on 31ST AUGUST-2017

PILING WORK IN PROGRESS BLOCK C06, C07, C08







PILING WORK IN PROGRESS BLOCK C06, C07, C08







PACKAGE-IV	STATUS AS ON 31/08/2017				
Block A01	100% Basement slab casting completed.				
UpTo Last Month					
Current Month	 Stilt floor columns casting work completed. 				
Activity	 First floor slab 50% shuttering and steel binding work in 				
	progress.				
Block B04	 Second floor slab casting 100% (8 flats) completed. 				
UpTo Last Month	 First floor brick work 100% (8 flats) completed. 				
Current Month	• Third floor slab casting 100% (8 flats) completed.				
Activity	• Fourth floor slab casting 50% (4 flats) completed.				
	• Second floor brick work 50% (4 flats) completed.				
Block B05	• Fourth floor slab casting 100% (8 flats) completed.				
UpTo Last Month					
Current Month	• Fifth floor slab casting 50% (4 flats) completed.				
Activity	 Remaining Fifth floor slab shuttering and steel binding 50% 				
	(4 flats) in progress.				
	• Third floor brick work 50% (4 flats) completed.				
Block C13	• Third floor slab casting 100% (4 flats) completed.				
UpTo Last Month	• First floor brick work 100% (4 flats) completed.				
Current Month	• Fourth floor slab casting 100% (4 flats) completed.				
Activity	• Fifth floor slab casting 100% (4 flats) completed.				
	 Second floor brick work 100% (8 flats) completed. 				
	Third floor brick work in progress.				
Block C14	• Fourth floor slab casting 100% (4 flats) completed.				
UpTo Last Month	• Second floor brick work 100% (4 flats) completed.				
Current Month	• Fifth floor slab casting 100% (4 flats) completed.				
Activity	• Sixth floor slab casting 100% (4 flats) completed.				
	• Third floor brick work 100% (4 flats) completed.				
	Fourth floor brick work in progress.				
Block C03	• P.C.C work completed.				
UpTo Last Month					
Current Month	• Pile caps casted 22 no's out of 44 no's.				
Activity	Stitch slab casting work in progress.				
Block C04	 Total 60 nos. of piles casted out of 194. 				
UpTo Last Month	Duran and the				
Current Month Activity	• Piling work in progress.				
· ·	• 140 piles casted out of 194.				
Block C05 UpTo Last Month	• Total 120 nos. of piles casted out of 195.				
Current Month	105 piles costed out of 105 completed				
Activity	• 195 piles casted out of 195 completed.				
Non Tower	P.C.C work in progress. Total 620 mag of piles costed out of 825				
	• Total 630 nos. of piles casted out of 825.				
UpTo Last Month	• 106 nos. Pile casting for STP completed.				
	 900 Sqm slab casting of extended basement completed. 				





Current Month	• 490 piles casting completed.
Activity	• 20 no's Pile caps casting completed.
	 300 Sqm stitch slab casting completed.
	• 500 Sqm slab casting completed.
Permission For	 Required permission obtained from the Mining Authority Greater
Excavation	Noida on12th April 2017.
Sample Flat Type	Paint work of walls & Ceiling completed.
B Status	Tile fixing work completed.
	Electrical work completed.
	 Water supply work completed.
	 Drainage and Sewage work completed.
Sample flat Type	Paint work of walls & Ceiling completed.
C Status	Tile fixing work completed.
	Electrical work completed.
	Water supply work completed.
	 Drainage and Sewage work completed.





PHOTOGRAPHS OF PACKAGE-IV on 31st August-2017

BLOCK A01: 50% SLAB STEEL & SHUTTERING WORK COMPLETED, READY TO CAST.







BLOCK B04: FOURTH FLOOR 50% SLAB CASTING COMPLETED.







BLOCK B05: FIFTH FLOOR SLAB CASTING COMPLETED.







BLOCK: B04, B05, A01, C13, C14 TOP VEIW







PACKAGE-V	STATUS AS ON 31/08/2017
Up to Last Month	• 50% 5 th Floor Roof slab casting done.
	 90% Brickwork done in Stilt Floor.
Block B01	• 80% Brickwork done in 1 st floor.
	 60% ceiling plaster done in Stilt floor.
	• 60% wall plaster done in 1 st floor.
	 100 % Sample flat plastering completed.
	 POP cornice work is completed.
	 One coat of Birla putty work completed.
	Water proofing work in Toilets is completed.
Current Month	• 75% columns casted at 7 th floor lvl.
Activity	 25% casting of 7th Floor Roof slab done.
	• 5% Brickwork done in Stilt Floor.
	• 15% Brickwork done in 1 st floor.
	• 95% Brick work done in 2 nd floor lvl.
	 25% Brickwork done in 3rd floor lvl.
	• 30% ceiling plaster done in Stilt floor.
	• 50% Ceiling plaster done in 1 st floor.
	Except Aluminum doors & windows sample flat work
	completed.
Up to Last Month	• 25% casting of 3 rd floor Roof slab completed.
Block B02	 90 % Brickwork completed in Stilt floor.
	• 25% ceiling plastering completed.
~	• 25% Brickwork completed in 1 st floor.
Current Month	• Balance 75% casting of 3 rd floor Roof slab completed.
Activity	• 100% casting of 4 th floor Roof slab done.
	• 100% casting of columns done at 5 th floor lvl.
	• 75% casting of 5 th floor Roof slab completed.
	• 70% Brick work completed in 1 st floor lvl.
	• 25% Brickwork done in 2 nd floor lvl.
TT 4 T 4 T 7 T	• 90% ceiling plaster done in stilt floor lvl.
Up to Last Month	• 100% casting of Basement Roof slab done.
Dlask D02	• 60% columns casted at Stilt floor lvl.
Block B03	
Current Month	400/ Calaman and A CANA March 1
Activity	• 40% Columns casted at Stilt floor level.
Up to Last Month	Balance 25% casting of Stilt floor done.
Block C15	• 100% casting of First floor done.
	• 25 % casting of 2 nd floor Roof slab casting completed.
	 25% Brickwork completed in stilt floor.
	 40% Brickwork completed in 1st floor.
	 100% Brickwork of Sample flat completed.
	 Wall conduiting work is in progress.





Current Month Activity	 Balance 75% casting of 2nd floor Roof completed. 100% casting of 3rd floor columns completed. 25 % casting of 3r^d floor Roof slab casting completed. 15% Brickwork completed in stilt floor. 50% Brickwork completed in 1st floor. 70% Brick work completed in 2nd floor level.
Up to Last Month Block C16	 100% casting of Stilt floor Roof slab completed. 25% Columns casted at 1st floor level.
Current Month Activity	 Balance 75% casting of columns at 1st floor lvl completed. 100% casting of 1st floor Roof slab completed. 80% Columns casted at 2nd floor level.
Up to Last Month Non Tower	 Piling work is completed. 98% stitch slab casting completed. 75 % columns casting completed.
Current Month Activity	 Basement Roof slab shuttering and Reinforcement binding work is in progress.
Up to Last Month Retaining Wall	 Piling work is completed. Casting of retaining wall upto a length of 155 mtr completed.
Current Month Activity	• 35 mtrs length of Retaining wall casting done.
Sample Flat	 Internal water supply and drainage work completed. Water proofing work completed. 100% Plaster work completed. Except Toilets Floor Tiling work completed. Wall putty work in progress.





PHOTOGRAPHS OF PACKAGE-V on 31st August-2017

IN BLOCK C-15 3RD FLR ROOF SLAB 4TH FLAT REINFORCEMENT BINDING WORK IN PROGRESS.
IN BLOCK C-16 2ND FLR ROOF SLAB TWO FLATS REINFORCEMENT BINDING WORK IN PROGRESS.







IN BLOCK B-01 7^{TH} FLR ROOF SLAB TWO FLATS REINFORCEMENT **BINDING IN PROGRESS.**


IN BLOCK B-02 5TH FLR ROOF SLAB 3RD WING SHUTTERING WORK IN PROGRESS.








IN BLOCK B-03 STILT FLOOR COLUMNS 100% COMPLETED.







OVERALL VIEW BLOCKS C15, 16, B-01, 2 & B-03







IN TYPE-C SAMPLE FLAT TILES FLOORING EXCEPT TOILETS COMPLETED.







QUALITY CONTROL

<u>DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS</u> <u>CONDUCTED AT SITE:</u>

S. No	Materials	Source From	Test Date	Tests done	Result	
1	Coarse Sand	Bajpur		Each truck	Sieve/ Silt	
2	Coarse Aggregate	Nagal		Each truck	Sieve Analysis	
3	Fine Sand					
4	Cement	Third party testing is being done				
5	Steel	Third party testing is being done				
6	RCC Cubes are bei	re being tested and Register is being maintained.				
7	Slump test conducted at site to insure workability if concrete.					

PHOTOGRAPH OF QUALITY CONTROL AT SITE

Slump Testing













Brick Compressive Strength Testing







20mm & 10mm Aggregate Testing







Cube Testing Of Concrete







Fine Aggregate Testing

