31st JAN- 2017

PACKAGE-II	STATUS AS ON 31/1/2017
Block D03	 Piling work is completed.
	 PCC work for foundation is completed.
	• Routine pie test done.
	 Integrity testing of piles done.
	 Stitch slab and grade beams casting completed.
	 Pile caps casting completed.
	 Column reinforcement binding work is in progress.
Block D04	 Piling work is completed.
	 Initial test of pile done.
	 PCC work for foundation is completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade beams & Pile caps reinforcement binding work
	is completed.
	Stitch slab Casting done.
Block D05	 Piling work is completed.
	 PCC work for foundation is completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, grade beams & pile caps reinforcement binding work
	is completed.
	 Placing and binding work of vertical reinforcement of columns is
71 1 704	in progress.
Block D06	 Piling work is completed.
	• PCC work for foundation 60% completed.
	Routine Pile test is done.
	 Remaining PCC work for foundation is in progress.
Block D07	Piling work is completed.
7 7.00	Kent ledge setup for routine test is completed.
Block D08	 Piling work is in progress.
	• Total 248 nos. of piles casted out of 256.
	 Kent ledge setup for routine pile test is in progress.
Non Tower	 Total 160 nos. of piles casted out of 631 nos.
Retaining Wall	 Total 27 nos. of piles casted out of 72 nos.





PHOTOGRAPHS OF PACKAGE-II on 31st JAN 2017


























PACKAGE-IV	STATUS AS ON 31/01/2017
Block A01	 Piling work is completed.
	 PCC work in foundation is completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab casting 50% completed.
	 7 nos. pile caps casting completed.
Block B04	 Piling work is completed.
	 PCC work in foundation is completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Columns casting upto basement roof level is completed.
	 Staircase casting is in progress.
Block B05	 Piling work is completed.
	 PCC work in foundation is completed.
	• Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Columns casting upto basement roof level is completed.
	• Basement roof slab casting 50% (4 flats out of 8 flats) completed.
Block C13	 Piling work is completed.
	 PCC work in foundation is completed.
	• Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Columns casting upto basement roof level is completed.
	• 16 nos. columns casting upto 1 st lift completed.
Block C14	Piling work is completed.
	PCC work in foundation is completed.
	• Routine pile test done.
	 Integrity testing of piles done.
	Stitch slab, Grade Beams & Pile caps casting completed.
	• 35 nos. columns casting upto basement roof level is completed.
	Basement Roof slab shuttering work is in progress.
Block C03	Piling work is in progress.
	 Total 83 nos. of piles casted out of 195.
	Routine pile testing completed.
Block C04	No work done.
Block C05	No work done.
	- 110 WOIR GOILC.






Non Tower	Piling work is in progress.
	• Total 312 nos. of piles casted out of 675.
	• 21 piles casted in STP.
	 Casting of pile cap, stitch slab and retaining wall footing is in
	progress.
	 Casting of Grade beams & Pile caps is in progress.
	 Kota stone cladding of outer side of retaining wall is in progress.

PHOTOGRAPHS OF PACKAGE-IV on 31st Jan 2017

























(A) SITE WORKS

PACKAGE-V	STATUS AS ON 31/12/2016		
Block B01	Piling work is completed.		
	 PCC work in foundation is completed. 		
	• Routine pile test done.		
	 Integrity testing of piles done. 		
	Stitch slab, Grade Beams & Pile caps casting complete	eted.	
	 Columns casting upto basement roof level is comple 	ted.	
	Reinforcement steel binding work of basement roof steel.	slab for two	
	flats is completed and further slab shuttering and bin	ding work is	
	in progress.		
	 40 cum concreting work of Slab in Non Tower portion 	on completed.	
	 Staircase casting is in progress. 		
Block B02	 Piling work is completed. 	Piling work is completed.	
	 PCC work in foundation is completed. 	PCC work in foundation is completed.	
	 Routine pile test done. 		
	 Integrity testing of piles done. 		
	 Stitch slab, Grade Beams & Pile caps casting comple 	eted.	
	 Columns casting upto 2.7 mtr is completed. 		
	 Columns casting upto 2nd lift is in progress. 		
	 Staircase shuttering work is in progress. 		
Block B03	 Piling work is completed. 		
	 PCC work in foundation is completed. 		
	 Routine pile test done. 		
		Integrity testing of piles done.	
	 Stitch slab casting 85% completed. 		
	 Reinforcement binding of Stitch slab 90% completed 		
	 Columns casting upto 1st lift is in progress. 		
Block C15	 Piling work is completed. 		
	 PCC work in foundation is completed. 		
	• Routine pile test done.		
	 Integrity testing of piles done. 		
	• 100 % Stitch slab, Grade Beams & Pile caps casting	-	
	 100 % columns casting upto basement roof level is c 	-	
	 Beam Shuttering for Basement Roof slab is in progre 	ess.	
	Staircase casting is in progress.		
Block C16	 Piling work is completed. 		
	 PCC work in foundation is completed. 		
	 Routine pile test done. 		
	 Integrity testing of piles done. 		
	 Stitch slab, Grade Beams & Pile caps casting complete 		
	 Columns casting upto basement roof level is comple 	ted.	





Non Tower	 Piling work is in progress. Total 405 nos. of piles casted out of 508. 	
Retaining Wall	 Piling work is in progress. 	
	 Casting of Retaining wall upto a length of 50 mtr completed. 	

PHOTOGRAPHS OF PACKAGE-V on 31st of Jan-2017



















