
31st MAR- 2017

PACKAGE-II	STATUS AS ON 31/03/2017
Block D03	Piling work completed.
	 P.C.C. work for foundation completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab and grade beams casting completed.
	 Pile caps casting completed.
	 All columns casted upto basement roof beam soffit level.
	 2 nos. of staircases three flights casted.
	 Shuttering work of basement roof slab of two flats out of four is
	in progress.
Block D04	 Piling work completed.
	 P.C.C. work for foundation completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab and grade beams casting completed.
	 Pile caps casting completed.
	• 12 nos. of columns casted upto 2400 mm height and 58 nos. of
	columns casted upto basement roof beam soffit level.
Block D05	Piling work completed.
	 PCC work for foundation completed.
	Routine pile test done.
	 Integrity testing of piles done.
	Stitch slab and grade beams casting completed
	Pile Caps casting is completed.
	• 35 nos. of columns casted upto 2400 mm height and 08 nos. of
	columns casted upto basement roof beam soffit level.
	 Remaining columns rings reinforcement steel binding is in
Block D06	progress.
DIOCK DOO	Piling work completed. PCC work for foundation completed.
	PCC work for foundation completed.Routine pile test done.
	 Routine pile test dolle. Integrity testing of piles done.
	 Stitch slab and grade beams casting completed
	 Pile Caps casting completed.
	 Columns rings reinforcement providing & binding is in progress.
Block D07	Piling work completed.
DIOCK DOT	 Initial Pile Test done.
	 Routine Pile Test done.
	 Routine File Test doile. Integrity testing of piles done.
	 80% PCC work is completed.
	 Casting of stitch slab 20% completed.
	 Layout of Pile caps is in Progress.
	 Reinforcement binding for Stitch slab and Pile caps is in progress.
	 PCC work is in progress.





PHOTOGRAPHS OF PACKAGE-II on 31st Mar-2017

































PACKAGE-IV	STATUS AS ON 31/03/2017
Block A01	Piling work is completed.
	 PCC work in foundation is completed.
	Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade beams & Pile caps casting completed.
	 75% Columns casting complete of 1st lift.
Block B04	 Piling work is completed.
	 PCC work in foundation is completed.
	• Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Columns casting upto basement roof level is completed.
	 One Staircase from basement floor to stilt floor completed.
	 45% Basement Roof slab casting completed.
	 Columns steel binding of Stilt floor in progress.
Block B05	 Piling work is completed.
	 PCC work in foundation is completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Basement roof slab casting 100% (8 flats) completed.
	 Stilt floor columns casting completed upto roof level.
	 Stair case from stilt floor to first floor level is in progress.
	 Stilt floor roof slab casting of 2 flats out of eight completed.
	 Steel binding of first floor columns is in progress.
	 Stilt floor roof slab Shuttering and Reinforcement steel work in
	progress for 2 flats.
Block C13	 Piling work is completed.
	 PCC work in foundation is completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Columns casting upto basement roof level is completed.
	 Shuttering and Reinforcement work of basement roof slab is in
	progress for two flats.
Block C14	 Piling work is completed.
	 PCC work in foundation is completed.
	Routine pile test done.
	• Integrity testing of piles done.
	Stitch slab, Grade Beams & Pile caps casting completed.
	• Columns casting upto basement roof level is completed.
	• Basement Roof slab casting 100% (4 flats) completed.
	 80% Stilt floor columns casting completed.





Block C03	Piling work is in progress.
	• Total 104 nos. of piles casted out of 195.
	Routine pile testing completed.
Block C04	Piling work is in progress.
	 Total 41 nos. of piles casted out of 194.
Block C05	 No work done as excavation permission is still is still to receive.
Non Tower	Piling work is in progress.
	• Total 409 nos. of piles casted out of 825.
	• 106 piles casted in STP completed.
	 PCC work in progress.
	 Casting of pile cap, stitch slab and retaining wall is in progress.
	 Reinforcement & Casting of grade beams & pile caps is in progress.
	 Kota stone water proofing work on outer side of retaining wall is in progress.
	 Columns casting in progress.
	• 200 Sqm slab casting completed of extended basement near Block B-05 adjacent to Jal Vayu Vihar society side.
	200 Sqm slab shuttering and reinforcement work in progress near block B-04 adjacent to Jal Vayu Vihar society side.





PHOTOGRAPHS OF PACKAGE-IV on 31st Mar- 2017

























PACKAGE-V	STATUS AS ON 31/03/2017
Block B01	Piling work is completed.
	 PCC work in foundation is completed.
	• Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Columns casting upto basement roof level is completed.
	 100% slab casting at basement roof level is completed.
	 100 %Columns casting at Stilt flr lvl is completed.
	 Staircase casting upto stilt Roof level is completed
	 Reinforcement steel binding work of Stilt Roof slab for 4 flats is
	in progress.
Block B02	Piling work is completed.
	 PCC work in foundation is completed.
	Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Columns casting upto basement roof level is completed.
	 Casting of Basement Roof Slab for 4 flats is completed.
	 Further shuttering and reinforcement binding work for remaining
	flats is in progress.
Block B03	 Piling work is completed.
	 PCC work in foundation is completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab casting 100% completed.
	• 100% Pile Caps casting done.
	 100% casting of columns upto Basement Roof slab beam bottom
	is completed.
Block C15	
	 Piling work is completed.
	 PCC work in foundation is completed.
	 Routine pile test done.
	 Integrity testing of piles done.
	 100 % Stitch slab, Grade Beams & Pile caps casting completed.
	 100 % columns casting upto basement roof level is completed.
	• 50% (Two flats) casting of basement roof slab is completed.
	 Reinforcement binding for two flats is in progress.
	 Staircase casting upto Stilt floor is done.
Block C16	 Piling work is completed.
	 PCC work in foundation is completed.
	• Routine pile test done.
	 Integrity testing of piles done.
	 Stitch slab, Grade Beams & Pile caps casting completed.
	 Columns casting upto basement roof level is completed.





Non Tower	Piling work is completed.
	• 90% stitch slab casting completed.
	• 95% PCC work is completed.
	 Reinforcement binding in Stitch slab is in progress.
	 Dressing work for PCC is in progress.
Retaining Wall	Piling work is completed.
	• Casting of Retaining wall upto a length of 85 mtr completed.
	 Reinforcement binding for wall is in progress.
	• Water proofing with Kota stone on outer side wall is in progress.
	• 2 nd lift casting of Retaining wall is in progress.





PHOTOGRAPHS OF PACKAGE-V on 31st Mar- 2017











16

