31st - JAN-2017

PACKAGE-II	STATUS AS ON 31/01/2018
Up to Last Month Block D03	 Balance 50% 12th floor Roof slab & 100% 13th floor Roof slab casted. 100% columns casted at 13th & 14th floor level. Balance 70% Brick work done at 9th floor lvl & 100% Brick work in 10th floor lvl completed. Balance 30% Plaster work at 3r^d floor lvl completed. 100% Plaster work at 4th & 5th floor lvl completed. 75% of Plaster done at 6th floor lvl. Door frames 100% fixed in 6th & 7th flr lvl. 100% cpvc piping work in 7th floor lvl completed. CI piping work in 8th floor lvl completed.
Current Month Activity Up to Last Month	 Terrace slab shuttering of two flats is in progress. 100% Brickwork done at 11th floor lvl. 50% Brick work done at 12th floor lvl. Balance 25% plaster done at 6th floor lvl. 100% plaster done at 7th, 8th & 9th floor lvl. 100% door frames fixed at 8th, 9th & 10th floor lvl. 100% Cpvc piping work completed at 8th & 9th floor lvl. CI piping work at 9th floor lvl completed.
Block D04	 Balance 38 columns casted at 9th floor lvl. 100% columns casted at 10th floor lvl. 46 columns casted at 11th floor lvl. 100% 9th & 10th floor Roof slabs casted. 11th floor Roof slab shuttering in progress. 100% Brick work completed at 3rd & 4th floor lvl. 100% Door frames fixed at 1st floor lvl.
Current Month Activity	 Balance 24 Columns casted at 11th floor lvl. 100% 11th & 12th floor Roof slab casted. 100% columns casted at 13th floor lvl. 13th floor Roof slab Reinforcement binding work of two flats in progress. 100% Brick work done at 5th floor lvl. 50% Brick work done at 6th floor lvl. 100% cPVC piping work done at 1st, 2nd & 3rd floor lvl.





Up to Last Month	
Up to Last Month Block D05 Current Month Activity	 100% 6th & 7th floor Roof slab casted. Balance 38 columns up to soffit of 6th floor Roof beams casted. 100% columns casted at 7th & 8th floor lvl. 8th floor Roof slab 50% casted. Balance 50% Brick work completed at 1st floor lvl. 100% Brick work in 3rd & 4th floor lvl completed. 100% door frames fixed in 1st floor lvl. 100% columns casted at 9th & 10th floor lvl. Balance 50% 8th floor Roof slab casted. 100% 9th floor Roof slab casted. 100% Brick work done at 5th floor lvl.
Up to Last Month Block D06	 Balance 54 columns casted up to soffit of 4th floor Roof beams. 100% columns casted at 5th floor lvl. 26 columns casted at 6th floor lvl. Balance 50% 3rd floor Roof slab & 100% 4th & 5th floor Roof slab casted.
Current Month Activity	 Balance 44 columns casted at 6th floor lvl. 100% columns casted at 7th floor lvl. 80% Columns casted at 8th floor lvl. 100% 6th & 7th floor Roof slab casted.
Up to Last Month Block D07	 Balance 25% Basement Roof slab casted. (Total 100% casted).
Current Month Activity	• 100% Stilt floor columns casted.
Up to Last Month Block D08 Current Month Activity	 Basement Roof slab 50% casted. Basement Roof slab Wing-01 shuttering work in progress. Balance 50% Basement Roof slab casted.
Up to Last Month Non Tower Current Month Activity	 400 Sqm Basement Roof slab casted. (Total 1090 Sqm casted.) 730 Sqm PCC work done. (Total 6800 Sqm completed.) 31 Pile caps casted. (Total 94 completed). 1700 Sqm Stitch slab casted. (Total 5900 Sqm). 100 sqm PCC done. 900 Sqm Stitch slab casted. (Total 6800 Sqm).
	 10 Columns casted. 12 Pile caps casted.





Up to Last Month Retaining Wall	• Retaining wall of 22 mtrs length casted in 1 st lift and 24 mtrs casted in 2 nd lift. (Total 78 mtrs casted).
Current Month Activity	• Retaining wall footing of length 30 mtrs casted.
Sample Flat Type-D	• All works completed except Aluminum Doors & Windows.

PHOTOGRAPHS OF PACKAGE-II on 31st JAN-2018

IN BLOCK D-03 TERRACE FLOOR SLAB REINFORCEMENT BINDING IN PROGRESS.







IN BLOCK D-04 13th FLOOR ROOF SLAB SHUTTERING IN PROGRESS.





Progress Report No. 21 (1st Jan- 18 – 31st Jan- 18)



IN BLOCK D-05 10th FLOOR ROOF SLAB REINFORCEMENT BINDING IN PROGRESS.





Progress Report No. 21 (1st Jan- 18 – 31st Jan- 18)



IN BLOCK D-06 COLUMNS CASTING AT 8th FLR LVL IN PROGRESS

IN BLOCK D-07 100% STILT COLUMNS CASTED.







PACKAGE-III STATUS AS ON 31/01/2018					
Up to Last Month Block C06	Basement columns 100% casted.Basement Roof slab shuttering 20% completed.				
Current Month Activity	 Basement roof slab100% casted. Stilt floor lvl columns 50% casted. 				
Up to Last Month Block C07	70% Pile caps casted.70% stitch slab casted.				
Current Month Activity	 100% stitch slab casted. Basement column 100% casted. Basement roof slab shuttering 50% completed. Basement roof slab reinforcement work is in progress. 				
Up to Last Month Block C08	Basement Roof slab Wing-1 casted.Wing-4 down portion casted.				
Current Month Activity	 Basement roof slab 100% casted. Stilt floor roof slab 100% casted. Column at 1st floor lvl 75% casted. 1st floor roof slab shuttering 30% done. 				
Up to Last Month Block C01	• Balance 59 piles casted (Total 100% casted)				
Current Month Activity	Piles 100% casted.PCC 30% done.				
Up to Last Month Block C02	• Excavation and dressing in Progress.				
Current Month Activity	 PCC 100% completed. Both lift Pit casted. Pile cap & stitch slab reinforcement 25% done 				
Up to Last Month Block C12	• 99 Piles casted. (Total 195 casted.)				



Progress Report No. 21 (1st Jan- 18 – 31st Jan- 18)



Current Month Activity	• 100% piles casted.			
Up to Last Month Block C11	• Total 73 piles casted.			
Current Month Activity	• 83 pile casted out of 195 no's piles			
Up to Last Month UG Tank	• 26 nos. piles casted. (Total 95 casted).			
Current Month Activity	 100% piles casted. 100% pile cap casted. 			
Up to Last Month Non Tower	 122 Piles casted. (Total 268 Casted). 8.5% Stitch slab casted. 21 mtrs Retaining wall casted. 			
Current Month Activity	 472 piles casted. 55 mtrs retaining wall casted. 12.77% stich slab casted. 11.49% column casted. 			





PHOTOGRAPHS OF PACKAGE-III on 31st JAN-2018

IN BLOCK C-06 STILT FLOOR ROOF SLAB SHUTTERING IN PROGRESS.

IN BLOCK C-08 1ST FLOOR ROOF SLAB SHUTTERING IN PROGRESS.







IN BLOCK C-07 BASEMENT ROOF SLAB SHUTTERING IN PROGRESS.







PACKAGE-IV	STATUS AS ON 31/01/2018			
Block A01	• 100% Fifth Floor slab casting work completed.			
UpTo Last Month	• 100% columns casting from Fifth to Sixth floor completed.			
	• 100% First floor brick work completed.			
Current Month	• 100% Sixth Floor slab casting work completed.			
Activity	• 100% columns casting from Sixth to Seventh floor completed.			
	• 100% Seventh floor shuttering work completed steel binding			
	in progress.			
	80% Second floor brick work completed.			
Block B04	• 100% Seventh Floor slab casting work completed.			
UpTo Last Month	• 25% Fifth Floor brick work completed.			
	• Third floor Plaster work in progress.			
	• Fourth floor Frame fixing work in progress.			
	• Fourth floor internal water supply work in progress.			
Current Month	• 50% Eight Floor slab casting work completed.			
Activity	• 100% Fifth Floor brick work completed.			
	• 80% Fourth floor Plaster work completed.			
	• Fourth floor Frame fixing work completed.			
	• Fourth floor internal water supply work completed.			
	Fourth floor internal wall conduiting work completed.			
Block B05	• 50% Ninth floor slab casting completed.			
UpTo Last Month	• 25% columns casting from Ninth to Tenth floor completed.			
	• Fifth floor brick work completed.			
	• Fourth floor plastering work in progress.			
	• Fourth floor door frame fixing work completed.			
	• Fifth floor internal water supply work in progress.			
Current Month	• Fourth floor Electrical internal wall conducting in progress.			
Activity	 100% Ninth floor slab casting completed. 100% columns costing from Ninth to Tonth floor completed 			
Activity	 100% columns casting from Ninth to Tenth floor completed. 70% Sixth floor brick work completed. 			
	 70% Seventh floor plastering work completed. 			
	 Fifth floor door frame fixing work completed. 			
	 Fifth floor internal water supply work in progress. 			
	 Fifth floor Electrical internal wall conducting in progress. 			
Block C13	 100% Eleventh floor slab casting completed. 			
UpTo Last Month	 Eight floor brick work in progress. 			
1	 First floor door frame fixing work in progress. 			
	 Fifth floor internal water supply work in progress. 			
	 Second floor Electrical internal wall conducting in progress. 			
Current Month	• 100% Twelve floor slab casting completed.			
Activity	 75% columns casting twelve to Terrace floor completed. 			
	Ninth floor brick work completed.			
	Third floor door frame fixing work in progress.			
	• Eight floor internal water supply work in progress.			
	• Fourth floor Electrical internal wall conducting in progress.			





Block C14	• 100% Twelfth floor slab casting completed.
UpTo Last Month	• Ninth floor brick work in progress.
	• Fourth floor plaster work in progress.
	• Sixth floor door frame fixing work in progress.
	• Eight floor internal water supply work in progress.
	• Sixth floor internal Electrical wall conduict work in progress.
Current Month	• 100% columns casting Twelfth to Terrace floor completed.
Activity	Terrace floor shuttering work in progress.
	• 75% Tenth floor brick work completed.
	• 70% Seventh floor plaster work completed.
	 Eight floor door frame fixing work in progress.
	• Eight floor internal water supply work completed.
	Eight floor internal Electrical wall conduit work in progress.
Block C03	• 100% Basement slab casting completed.
UpTo Last Month	• 50% Stilt floor columns casting completed.
Current Month	100% columns casting Stilt to First floor completed.
Activity	• 100% First floor slab casting completed.
	• 40% columns casting First to second floor completed.
Block C04	• 100% PCC work completed.
UpTo Last Month	• 100% Stitch slab & pile cap casting completed.
	• 40/50 Basement columns casting work completed.
Current Month	• 100% Basement columns casting work completed.
Activity	 100% Basement slab casting completed.
	 Stilt to First floor columns steel binding in progress.
Block C05	 30 no's Pile caps casting completed.
UpTo Last Month	 30/50 Basement columns casting work completed.
•	 75% Stitch slab completed & steel binding in progress.
Current Month	 100% Pile caps casting completed.
Activity	 30/50 Basement columns casting work completed.
e e	 Balance Basement columns binding work in progress.
Non Tower	 100% piles casting completed (825/825).
UpTo Last Month	 400 sqm NTA slab casting completed.
- F =	 25 M Retaining wall casting work completed.
	 Kota stone water proofing work in progress in retaining wall.
	 Basement round columns casting work in progress
Current Month	
Activity	 450 sqm Stitch slab casting completed. 150 sqm NTA slab casting completed.
	 220 mtr out of 314 mtr Retaining wall casting work completed.
	 150 mtr out of 314 mtr Kota stone water proofing work
	• 150 mtr out of 514 mtr Kota stone water proofing work completed.
	 Basement round columns casting work in progress
	 Dasement round columns casting work in progress





Sample Flat Type B & C Status	 Paint work of walls & Ceiling completed. Tile fixing work completed. Electrical work completed.
	Water supply work completed.Drainage and Sewage work completed.

PHOTOGRAPHS OF PACKAGE-IV on 31st JAN-2018

IN BLOCK C-13 COLUMNS CASTING AT 12TH FLOOR LVL IN PROGRESS & IN BLOCK C-14 TERRACE FLOOR SLAB SHUTTERING IN PROGRESS.







IN BLOCK C-03 1ST FLOOR ROOF SLAB SHUTTERING IN PROGRESS.







IN BLOCK B-04 8TH FLOOR ROOF SLAB REINFORCEMENT BINDING IN PROGRESS & IN BLOCK B-05 9TH FLOOR ROOF SLAB REINFORCEMENT BINDING IN PROGRESS.







IN BLOCK A-01 7TH FLOOR ROOF SLAB REINFORCEMENT BINDING IN PROGRESS.







PACKAGE-V	STATUS AS ON 31/01/2018
Up to Last Month	• Terrace slab shuttering is in progress.
	• 90% Brick work done in 7 th & 8 th flr lvl.
Block B01	• 90% Plaster done in 5 th flr lvl.
	• 40% Plaster done in 6 th floor lvl.
	• 100% Door frames fixed in 6 th floor lvl.
	• 100% cPVC piping work done in 6 th & 7 th floor lvl.
	• CI piping work in 5 th floor lvl completed.
	• Water proofing in 3 rd floor lvl completed.
	• POP cornice 1 st , 2 nd , 3 rd floor lvl completed.
Current Month	• Terrace slab 30% casted, further area shuttering &
Activity	reinforcement work is in progress.
	• 25% stub columns casted.
	• 100% Brick work done at 9 th floor lvl.
	• 80% Brick work done in 10 th flr lvl.
	• 90% Plaster done in 7 th floor lvl.
	• 90% Door frames fixed in 7 th floor lvl.
	• 90% cPVC piping work done at 8th & 9th floor lvl.
	 CI piping work in 7th floor lvl completed.
	 Water proofing in toilet sunken area in progress from 1st to
	3^{rd} floor.
	• POP cornice completed up to 6 th floor.
Up to Last Month	 100% columns casted at 12th floor lvl.
Block B02	 75% columns casted at 12 moon fvi.
	 100% 11th & 12th floor Roof slabs casted.
	 90% Brick work done in 8th & 9th floor lvl.
	 90% Plaster done in 4th & 5th floor lvl.
	 45% plaster done in 6th floor lvl.
	 100% Door frames fixed in 6th & 7th flr lvl.
	 100% Dool frames fixed in 6° & 7° fit fvi. 100% cPVC piping done in 7th & 8th floor lvl.
	 CI piping done at 5th floor lvl.
Current Month	• CI piping done at 5 moor ivi.
Activity	Balance 25% columns casted at 13 th floor lvl.
Activity	
	 Terrace slab shuttering is in progress. 90% Brick work done in 10th floor lvl.
	 Balance 45% plaster done in 6th floor lvl. 90% Plaster done in7th floor lvl.
	• 25% plaster done in 8 th floor lvl.
	• 90% Door frames fixed in 8 th flr lvl.
	• 90% cPVC piping done in9th & 10 th floor lvl.
	• CI piping done at 7 th floor lvl.
	• Water proofing in toilet sunken area in progress from 1 st to
	3 rd floor.
	• POP cornice completed up to 3 rd floor lvl.
Up to Last Month	• 100% columns casted at Stilt flr lvl.
Block B03	
Progr	ess Report No. 21 (1 st Jan- 18 – 31 st Jan- 18) 🛛 🔰 🗕 🦵



Current Month	
Activity	
Up to Last Month	
Block C15	• 100% columns casted at 7 th floor lvl.
	• 75% columns casted at 8 th floor lvl.
	• 100% casting of 7 th floor Roof slab done.
	• Balance 20 % Brick work done in 4 th flr lvl.
	• 90% Brick work done in 5 th flr lvl.
	• 90% plaster done in 3 rd & 4 th floor lvl.
	• 100% Door frames fixed in 3 rd & 4 th floor lvl.
	• 100% Cpvc Piping work done in 3 rd & 4 th floor lvl.
Current Month	• Balance 25% columns casted at 8 th floor lvl.
Activity	 60% columns casted at 9th floor lvl.
	 100% casting of 8th floor Roof slab done.
	 90% Brick work done in 6th flr lvl.
	 20% brickwork done in 7th floor level.
	 90% Door frames fixed in 5th floor lvl.
	• 90% Cpvc Piping work done in 5 th floor lvl.
	POP cornice completed up to 4 th floor lvl.
Up to Last Month	
Block C16	• 100% columns casted up to soffit of 5 th & 6th floor Roof beams
	bottom.
	• 100% casting of 6 th & 7 th floor Roof slab done.
	• 25% 8 th floor Roof slab casted.
	• 90% Brick work done in 2 nd floor lvl.
	• 90% Plaster done in 1 st floor lvl.
Current Month	
Activity	 100% columns casted at 7th & 8th floor lvl.
	• 80% column casted at 9 th floor lvl.
	 100% casting of 8th floor Roof slab done.
	• Terrace slab shuttering work is in progress.
	• 70% Brick work done in 3 rd floor lvl.
	• 20% Brick work done in 4 th floor lvl.
	• 90% Door frames fixed in 1st floor lvl.
	 90% cPVC piping done in 1st floor lvl.
Up to Last Month	
Non Tower	• 1250 Sqm Basement Roof slab casted. (Total 2700 Sqm casted).
	- 1250 Sqiil Busement Roof shub custod. (10tai 2700 Sqiil custod).
Current Month	1395 Sqm Basement Roof slab casted. (Total 5095 Sqm
Activity	casted).
	custou).
Up to Last Month	Retaining wall of length 55mtrs casted.
Retaining Wall	• •
iveranning wall	• Water proofing (Kota stone) on outer side of Retaining wall in progress
	progress



Progress Report No. 21 (1st Jan- 18 – 31st Jan- 18)



Current Activity	Month	 Retaining wall of length 25 mtrs in 2nd lift casted. (Total 190mtrs casted). Water proofing (Kota stone) on outer side of Retaining wall in progress 	
Sample	Flat		
Type-C		• Paint work of walls & Ceiling completed.	
		• Tile fixing work completed.	
		• Electrical work completed.	
		• Water supply work completed.	
		• Drainage and Sewage work completed.	
		Chinaware fixing done.	
		• CP fittings is pending.	

PHOTOGRAPHS OF PACKAGE-V on 31st JAN-2018

IN BLOCK B-01 TERRACE FLOOR SLAB REINFORCEMENT BINDING IN PROGRESS.







IN BLOCK B-02TERRACE FLOOR ROOF SLAB REINFORCEMENT BINDING IN PROGRESS.







IN BLOCK C-15 COLUMNS CASTING AT 9TH FLOOR LVL IN PROGRESS.







IN BLOCK C-16 TERRACE FLOOR SLAB SHUTTERING IN PROGRESS.







QUALITY CONTROL

DURING CONSTRUCTION FOLLOWING QUALITY CONTROL TESTS CONDUCTED AT SITE:

S. No	Materials	Source From	Test Date	Tests done	Result	
1	Coarse Sand	Bajpur		Each truck	Sieve/ Silt	
2	Coarse Aggregate	Nagal		Each truck	Sieve Analysis	
3	Fine Sand					
4	Cement	Third party testing is being done				
5	Steel	Third party testing is being done				
6	RCC Cubes are being tested and Register is being maintained.					
7	Slump test conducted at site to insure workability if concrete.					

PHOTOGRAPH OF QUALITY CONTROL AT SITE

IIT ROORKEE CONDUCTED QULATIY TESTS AT SITE







IIT ROORKEE CONDUCTED QULATIY TESTS AT SITE







IIT ROORKEE CONDUCTED QULATIY TESTS AT SITE







IIT ROORKEE CONDUCTED QULATIY TESTS AT SITE







Brick Compressive Strength Testing







20mm & 10mm Aggregate Testing







<u>Cube Testing Of Concrete</u>







Fine Aggregate Testing





