

BLOCK NO - A-01

Block - A-01

Date 12-03-2021

Page No.

12-03-2021

Sr. No.	Flat No.	Name of Allottee	Mobile No.	Remarks.
1	804	SANJAY		Excellent
2	806	Y.S. Rawat		v. Good
3	508	A-1107		Good
4	1107	Arushi Sin		Very Good
5	103	Reva		Good
6	105	Jaymeet K		Nice location & Construction, Good
7	107	Shubh		Good
8	203	Rosabiraj		v. Nice and Good.
9	808	Manoj		Have to done more work
10	1404	Nalanda		v. Good
11	108	Lakshay		Excellent.
12	706	Ri P. Verma		v. Good
13	701	Richa		Excellent
14	802	kishore kr choudhary		Excellent
15	1002	Ashok Keeman		v. Good
16	701	Runeet tripathi		Good
17	1401	Vijay Kumar		v. Good
18	705	Jyoti Rathi Sabharwal		Excellent
19	1106	Vikas Chandra Vidyarthi		Very Good.
20	606	Rajender Prasad		really very well designed.
21	1102	Ram Milan		Thank you.
22	106	Vaibhav Bajaj		Excellent
23	107	Kamla		v. Good
	207	Uttam Singh		Excellent
24	403	A.K. Joshi		v. Good

218
23/03/21

S.No	Name	Block & Flat No.	Mob.
16	B. N. Prasad.	B1 404	
17	N. K. Paikaray	B1-1006	
18	Mrs Sujatha. K C.	B-1 1106	
19	SANJAY KUMAR	B-1, 205	
20	Rinku Awang	B-1, 401	
21	Mavalal gada	B-1 1002	
22	Chandu Shekhawat	B-1, 701	
23	Mrs M. KRISHNA PRIYA	B-1/803	
24	Mr. Rajendra Chaudhary	402	
25	Sunil Kumar	B1/405	
26	Pradeep Kumar	B1 801	
27	Manish. C. Vaish	B1 507	
28	ASHOK KUMAR	B1-807	
29	J. Nagan	B, - 1005	
30	Bhanu Bhanu	B1-107	

Remarks

26th Provision of natural light is not good.

N/P Good work and the staircase layout

AB V-Good work and sanitaryware layout

CA Excellent

Rinky

CA

Beautifully designed and especially my first direction is north east which I was old service really very been & could be provided.

SA

AK Looking good.

MA: Entrance door wood broken, tiles needs proper joining & needs proper finishing.

A Beautiful design and wonderful design

MA → Beautiful and hard work and maintenance

MA Very Good flat

14/08/2021

Block

B-01

DATE

PAGE

DATE

PAGE

S.No	Name	Block + flat No.	mob.	Remarks
1-	VIKAS PATHAK	106 B-1		Satisfactory
2-	Manuata	408 "		Mr Chatur fully satisfied with the very good Dedup by Him - \leftarrow Please to capture as per sample flat shown earlier.
3-	Vikal Bharti	1107 "		Shri Rama Shaker expressed in very nice way.
4-	SUBHASH GUPTA	1103 "		Flat seen it's not fully finished. Rail gate is not available as per sample flat.
5-	Amit Kumar.	805 "		Nice flat. Thanks.
6-	ASHOK KUMAR	301		Nice flat, Chetan is very good person
7-	Raman Singh	B-506		Lot of works pending.
8-	AR PUSHPATAN	704 (B1)		I am very glad with the flat allotted.
9-	Dipankar Ghosh.	207 (B1)		Very satisfied, especially assisted by Sh. Rama Shaker.
10-	TAUSH B. PRASAD	201		Satisfactory.
11-	Punit Kumar	706		Nicely done, but yet to complete finishing.
12-	Niran Yadav	601		Very beautiful interior & location.
13-	ANISH JAIN	1108		Nice
14-	Jurendra Pal Tripathi	406 1315		
15-	ANAND MISHRA	907		



S.No.	Name	Block & Flat No.	Mob.	Remarks
1.	Jayendra Singh	B-2, 202		Just allotted work to be completed. otherwise excellent
2.	Vandana Raut	B-2 106		Satisfactory, however lot of work is to be done!
3.	R. S. RAM	B-2 107		3rd flt an an anu agt 2nd flt
4.	Dr. Dinkar Singh	B-2 607		Very satisfied. Good quality work. Thanks
5.	JOSEPH	B2 604		
6.	Anand Kumar	B2 802		Excellent and satisfactory. Person present here every 2022
7.	Sushil Kumar	B-02, 1101		Excellent flat
8.	Girish Singh	B-02 1108		Excellent flat, happy with quality of work
9.	Vijay Bhaskar	B-2 - 305		
10.	Raghav Ratan	B2- 602		Very satisfied with quality of work.
11.	SUD ZAKIR ALI	B2- 803		Satisfied but need quality check and repairing.
12.	TANISH B. PRASAD	B2- 403		Fully satisfied with active assisted by Sevik, Thanks.
13.	BRJESH KUMAR	B2- 901		
14.	Govind Singh	B2- 1403		Average but for viewing of sand not seen the actual flat but to lift
15.	Anitha Jayakumar	B2- 1007		

S.No.	Name	Block & Flat No.	Mob.
16.	Ironela Tirkey	B-2 1208	
17	Vijay Kr	B-2 408	
18	K N Prasad	B-2, 905	
19.	Raj Singh Chauhan	B-2 207	
20	Anil Bhat	B-2 603	
21	MAHINDER KUMAR	B-2 1003	
22	BHARATI KUKRETE	B-2 108	
23	Rachna Pathak	B-2 706	
24	Beena Pathak	B-2 701	
25	Ravindra S.P.	B-2 102	
26	Yash Srivastava	B-2 807	
27.	Pooja	B-2 - 1405	
28	Rishi Kr	B-2 - 1407	
29	Sudhir	B-2 907	
30	Natasha	B-2 1204	

Remarks

Excellent service in showcasing the apartment. Thanks Ag

me first

14/6/2024

Flat's are looking good. Shell completed well. Some work in future too. Best wishes. Mahesh

Hope, all allottees will get possession letter soon after completion of all pending work. Ag

Project seems on track. We are excited to ^{start} move in

I am satisfied with this project.

Interest to college, work quality is very very poor.

completion work need to be expedite, Ag

SN	Name	Block & Flat no.	mob.
30.	G. JOSHI	B2-1201	
31.	Sudhakar	B2 705	
32.	C.P. Pamar	B-02-1402	
33	Gopal Singh	B02 1104	
34	Sai Lal	B-02 1006	
35	Shashi Bhatnagar	B-02 - 606	
36	P.N. S.	B02 - 1107	
37	P. Arundhan	B-02 - 1207	
38	Srinivas Parvathi	B-02 808	
39.	R.K. Saha	B-2 605	
40	Suman Nandan	B-2 1209	
41.	Laxmi Parvati	B-2 804	
42	Dr. Hemlata	B-2 704	
43	Beena Singh	B-2 502	
44	Abhinav Bajpai	B2 - 506	
45.	Rajesh	B2 - 603	

Remarks

Work still to be done. Very good view.

Very Excellent ^{work} & Very good finishing.

Very good but not finished yet

Very good but not well completed

Very good location & view.

Excellent makeup. Great to watch. Hope to be here soon.

Satisfactory. I am happy.

Good

V. Good - 14/03/2021

Very nice :) Abhinav

[Signature]

o
2
Date = 14/03/21

BLOCK = B-03

Block B03:-

S.No.	Name	Fltno.	Contact no.	Remarks	Feedback
1	Rajesh Arora	103		R.A.	
2	MOHIT AVTA	1207		ms	
3	R. S. Arora	203		ms	Helping and cooperative nature. Appreciated Excellent.
4	Dushyant	407		ms	
5	N. A. Bhalesrao	207		ms	Staff helping ^{staff} and behaviour wise Excellent.
6	ASHIM BARUA	108		ms	
7	Brijm Kumar	901		ms	
8	Sudh Singh	1108		ms	
9	Amrita Rawat	1002		ms	
10	AB VERMA	508		ms	Staff were very cooperative. Feat is found to be good in construction.
11	Bhaskar Arora	304		ms	
12	SS Rawat	302		ms	Request make provision for jilly split in ^{bed room}
13	Ganga Devi Lalwal	907		ms	
14	Chauhan Singh	202		ms	Very cooperative staff excellent construction.
15	Vinay Solanki	807		ms	
16	A. Chaurah	1209		ms	Very good staff.
17	Gourav Chaturvedi	601		ms	
18	Meng Kumbhara	1104 104 B3		ms	main entry door lock is poor (pattern). staff cooperative.
19	Ramesh Dutt	104		ms	
20	Sheetal Kumar	1401		ms	
21	Ajay Kumar	708		ms	
22	Hari Singh	1402		ms	
23	R.V. Chaturvedi	1102		ms	
24	Ramendra	1008		ms	
25		1005		ms	
26	Chetan Singh	1903		ms	
27	Sudh Kumar	703		ms	
28	Saurabh Singh	302		ms	
29	Manoj	805		ms	
30	Jatinder Kumar	909		ms	Wall plaster & door jilly not adequate - 2nd am

5

14-03-2021

B03

BLOCK-B03

Remarks.

S.No.	Name	Flat No.	Cont.	Shg.
31.	R. Samana	1106	8	8/11
32	S. Khan	305	8	8/11
33	Rajesh Jain	1001	155	8/11
34	Hansa Singh	701	8	8/11
35	Susheela Devi	607	7	8/11
36	M. K. Prakash	1405	8	8/11
37	P. K. Tiwari	904	8	8/11
38	Mukesh Kumar	702	8	8/11
39	H. P. Gupta	1205	8	8/11
40	Shiv Deyyal	308	8	8/11
41	C.B. Sush	705	1	8/11

BLOCK NO - B-04

14-03-2021

S.No FIAT NO Name of A/c Mob. No

Remarks -

01 1208 SURESH MISHRA

Very Good Construction than fully it
ood project and Country Staff.
Infrastructure is very good.

02 804 MRAGHU

03 202 Rajiv Sindh

04 406 Satender Prusa

mt. of Plat is near completion
the price value it looks ok.
Staff present were cooperative

05 ~~1008~~ Jai Kumar

Nice observation given by the
executives. Thanks,
Township Engineer

6 703 Jai Kumar

Seems nice flat.

07 804 Armit Kumar

08 ~~1008~~ Parveen V. Nale

v. nice.

09 1101 Akhwar Prada

v. good.

10 602 A K Dal

Plat seems good.
Officials tested electrical system
found in good condition. Now needs final
finishing as per approved plan.
very good.

11 308 M.S. Chharwee

12 201 MR RICHARD S

very nice.

13. 1402 Anant K. Jai

very good.

14 806 Emerald

Nice.

15 1102 Sumati

It is good, but lack of
unlight. (Both toilets ^{will be} western
style) have is. Sewage
will in master bath room.
very well

16 1003 K.K. Neema

17 904 Dignijay Pa

very nice, excellent.

18 1104 Alex Singh

19 604 Rinky

20 501 Mahendra

Excellent

21 404 Shalini

Excellent.

22 901 Kavita

23 1007 Rinku

Good, nice scene.

v. good location

BLOCK NO - B-05

14-03-2021

Block - B-05

S.No.	Flats No.	Allottee Name	Mobile No.	Remarks
1	1204	T.S. Agarwal		rain. Needs petty work at places.
2	503	Vikash Kumar		built yet required finishing touch but floor work.
3	402	Deepak Sharma		Numbering is wrong of 2108 in same floor. 2102 must be adjoining. If still not working at the Numbering of floor is wrong as 101 & 108 call.
4	801	Deepak Sharma		
5	102	P.K. Ghosh		
6	502	Neelam Arora		cen. Not good
7	706	Binala Kataria		city is taking final shape beautiful.
8	504	Subhakar Arora		at unfinished, all take another 5 months.
9	1006	Mukh Khanna		to be finished
10	1206	Secara		nic'ent
11	1406	Nayshwar Prasad ^{Singh}		very good look
12	606	Sonjay Banerjee		od; minor repair work to done.
13	201	Babu Pandey		very Good. <u>nil</u> .
14	203	Madan Mishra		got complete overall good
15	505	Manu Singh		very Good but work to get completed
16	108	Khushal Singh		road
17	806	Kal Singh Khanna		road

BLOCK-804

BLOCK-804

Date _____
Page No. _____

S.No	Flat No	Name of Aitee	Mob. No	REMARKS-	S.No	Flat No	Name of Aitee	Mob. No	REMARKS-
24	902	K.V. Siddhesh		Flat is okay. Staff well-behaved. Request to kindly complete the remaining work soon as 9 am is close before bringing in the steel house.	41	207	Surej Bala		Excellent
25	408	Prem Kum		very well behaved staffs.	42	1108	Smriti Bai		v. good.
26	204	Ramesh Rai		Good to see the floor.	43	1107	Mamlesh Jain		good. practices v. good.
27	102	R.S. Raghavan		Good	44	606	RAMKISHAN SINGH		wash room tile not properly design. tile is not right side door and very small in size.
28	706	SUGAM TRIK		v. good.	45	208	BARAJ RAVI GIRI		Excellent work
29	808	J.R. Thakur		Excellent work	46	303	Kailash Ched		v. good.
30	1205	D.K. Sharma		v. good.	47	204	D.K. Joshi		v. good.
31	0905	S. Basu		pts of block to be carried out. Time will take long.	48	105	Harshit		Excellent.
32	1404	S.N. SANGH		Hope job will finished on appropriate time of taking over shawl.	49	1406	IR ANSARI		Perfect.
33	1207	Yashwant		Okay.	50	506	Harsh		Excellent
34	402	Surinder K		very good.	51	505	Anurag Singh		Good work. Location: Not Sun Face
34	608	Anil Kumar		v. nice.	52	504	C.P. SINGH		
35	201	Nilesh Kumar		very well behaved staff.	53	1006	SONAM BALI		
36	903	Satish Kumar		Grill should be provided in bed room without balcony.	54				
37	607	Sunil Thadar		Quality of work is very poor in 802. Work. make also poor. Sider tiles quality very poor. Finishing work is not done properly.					
38	802	Ghanshyam Sir							
39	605	Ajay Bhande							
40	1209	Ramkumar Kuro		good location					

BLOCK NO - B-05

14-03-2021

Block - B-05

S.No.	Flats No.	Allottee Name	Mobile No.	Remarks
1	1204	T.S. Agarwal		Needs petty work at place.
2	503	Vikash Kumar		Wt. yet, required whip touch but to remark.
3	402	Deepak Sharma		making 4 wrong 2108 in same floor. 102 must be adjoining fill net working
4	801	Deepak Sharma		Numbering of floor is wrong as 102, 108 at.
5	102	P.K. Ghosh		
6	502	Neelam Arora		en. Not good Chal
7	706	Bimal Kumar		city is taking that shape beautiful
8	504	Subham Arora		at unplug lead, 11 take another hands, see to be pushed &
9	1001	Mak Khanna		
10	1206	Seema		ok/ent
11	1406	Nageshwar Prasad		ry good look
12	606	Sonjay Banerjee		; minor repair work to one.
13	201	Basu Pandey		y Good (ND)
14	203	Madan Mishra		at complete overall good
15	505	Man Singh		y Good but work to set up complete
16	108	Khushal Singh		ed Basu
17	806	Lat Singh Khosla		ed / 1/1/1/

S.No.	Flat No.	Name of Alocer	Mobile No.	Remarks	S.No.	Flat No.	Name of Alocer	Mobile No.	Remarks
18	906	Shiv Kishore		Good Condition & prime location	35	306	Santosh Kalyan		Very good
19	805	Durgesh Sahani		Good location	36	404	Puttapalaka		Very Good.
20	702	Vinay Kumar			37	1107	Shailendra Shaha		V. Good
21	308	D.K. Srivastava		waterwise Excellent flat	38	104	Ashish Upadhyay		Good response from staff
22	1004	Ram Anand			39	504	C.P. Singh		Very Good <u>flat</u>
23	405	G.S. Negi			40	602	Brijbhairav		Very good <u>flat</u>
24	1007	P.N. Prasad		good location.	41	907	Chandankumar Salwa		Very good <u>flat</u>
25	904	Anam Verma		Seepage in room					
26	2708	Shankar Lal		light is good but corridor light is not enough					
27	508	Balram Verma		Good in context. special req.					
28	1005	Surendra							
29	608	Hari Mishra		looking good. Hot hot 14/3/21					
30	707	Dhruv Manro		Excellent					
31	204	Shelley							
32	206	Mohit Pal		Monthly very Impressed level 3!					
33	103	Ajay Verma		location is very good and works to improve					
34	207			Excellent 14/3/21					

BLOCK NO - C-02

13-04-2021

Block-C-02

S.No	Flat No.	Name of Alocsee	Mobile No.	Remarks
1	804	Rahul		Nice experience
2	1002	Gaganendra		Very good experience
3	401	Vinit Mishra		Satisfied with the experience with Mr. Satish Jaiswal
4	803	P.R. Singh		
5	902	Vishal Mishra		
6	301	R.M. Ghildiyal		Good construction
7	802			
8	201	Nisha Gupta		
9	1203	Mr. Sugriva Singh		Very good and well constructed & well finished.
10	703			
11	801	Pr. V. Nay		Nice job.
12	404	Vijay Jami		Not upto the mark, not as per plan.
13	703	Manisha Aggarwal		
14	104	Sanjiv Khosla		Good quality work maintained
15	1201	Ashok Sharma		
16	1003	Anoop Kumar		
17	704	Laxmi Mishra		Very good, very good construction
18	142	Ashwini Mishra		Very nice. Ashwini Mishra
19	701	Mahesh Chauhan		Work is good but finishing repair required.
20	401	Nagendra Singh		Location is good
21	1503	Shalendra Mishra		Work is well in position
22	303	A. C. Sengupta		Very good.
23	1504	M.P. Bhatia		Good construction
24	102	Gaurav Mishra		All good.
25	504	Pushpa Singh		
26	103	(Prof.) Satyamani		Satisfied. It's great to be here. lovely house
27	802	Dr. K. Tewari		The flat is good. Location is good. Work is good. Location is good. Work is good.
28	302			

13/3/21

5

Block - C-3

Block - C03

Date 13-3-2021

Flat No. 802 ⇒ 9th floor (Donut)
 Flat No. 603 - Rishi.

S.No	Flats No.	Name of Aleru	Mobile No.	Remarks !!
1	1501	Sameer Vyas		Satisfactory
2	303	Md. Said		Good.
3	1203	Kavita Dutt		V. good.
4	1104	Vijay Kr. Verma		Good.
5	402	Niraj Kishor		Best work. Completely satisfactory.
6	502	Romdoyal me		
7	1002	Manish B.		Satisfactory
8	601	Mogun Ali		Satisfactory.
9	301	V. Sreenivas		Satisfactory.
10	304	Chaitan		Satisfactory
11	101	Sk Agnihotri		Good.
12	802	Prabhat Parkash		Very friendly
13	1102	Ansona Dusey		Good
14	1401	Kamal Sharma		Very cooperative
15	302	Dr San deep		Very good
16	1101	Dr Ramnirja		Good
17	504	Sudhakar		Good, Equal work
18	402	Sneha Latta		Good
19	604	Rishi		
20	603	B.D. Belkar		Good
21	1103	Sudhar Nayar		Good
22	1203	Subhan gang.		Good
23	703	Am Choudhary.		
24	1503			
25	103	Niraj Kumar		
26	904	Rishi		
27	1004	Mary B. Barla		
28	1003	Praveen Ch. Mehta		

Block - C - 04

Date _____
Page No. _____

13/03/2021

S.No.	Flats No.	Name of Alok, Mobile No.	Remarks
1	1404	Lakshmi Shastri	- Bill unpaid, good view.
2	304	Rajy.	v. good.
3	903	Vijay Kumar	V. good view. ^{Support by 10/10}
4	204	A.K. Sanyal	Excellent.
5	1103	Dr. A.K. Jais	Lift is needed Flat v. good.
6	501	P. K. Sharma	good
7	801	Vijay Sharma	good
8	901	Jayashankar S.	
9	404	ARVIND SIM	v. Good
10	603	Umesh Kumar	V. Good
11	302	Mangal Ratan	
12	902	R.V. Sharma	Insufficient for me and location v. good
13	1201	RATIKA BA	also v. good.
14	104	Deepank Bhat	v. good.
15	804	Ram Kumar S.	v. GOOD
16	502	Ramesh Chandra	good v. good
17	1402	Manish Gupta	v. Good
18	303	P.P. Sharma	Excellent
19	1501	Anil K. Gupta	good
20	1001	Om Prakash	6 app Good
21	501	Nalini Dubey Srinath D.	Shalabh Dubey Very nice.

Date _____
Page No. _____

13-03-2021

S.No	Flats No.	Name of Alokia	Mobile No.	Remarks
1)	1004	Jai Shree		looks good. But many more works are yet to be worked out.
2)	802	Kamal		Beautiful mixture & cup i/pal
3)	301	Pranav Sharma		Very Nice Thank
4)	904	R.K. Srinan		Very nice floor
5)	109	Gaithi Kumar		very well designed!
6)	303	Nirmala Sankar		D.K. By
7)	703	Rakesh Kumar		Nice Rakesh!
8)	1204	Abhinav Gupta		Location is Good.
9)	702	Ryendrakumar		
10)	902	Kuldeep Abathi		Kuldeep & hope that will be given in June 2021
11)	401	Ramesh Lal		
12)	501	Shanki Arora		Good
13)	1104	Kanwar Dhal		Location is very good. Very good. Nice!
14)	903	Mamta Rawat		
15)	603	Neeraj Sharma		Very good. Nice!
16)	504	Seema Sahani		
17)	1009	Pratik Arora		Nice/Good Air space
18)	601	Anamika Kr. Das		Very much co-operating
19)	502	Devesh Kumar		
20)	403	DB VERMA		Shree. Good construction
21)	503	A.K. Upadhyay		V. Good response of staff
22)				
23)				
24)				
25)				
26)				
27)				
28)				
29)				
30)				
31)				

S.No	NAME	BLOCK / FLAT NO.	MOB NO	REMARKS
1	Vikas Bhatnagar			
1	Shyam Manikaranam	C/102 14		Very Good FOOD STAFF very good.
2	Seily Mishra	C-14-304		Food - 4/2
3	A.P.S. Kushub	C-14-402		6 days in 0 min / 247 at 21/03/21 49 Satisfying 747 Excellent ✓ Very good Excellent
4	Meebichhabra	C-14 902		
5	Pragya Sharma	C-14 403		
6	Usha Kumari	C-14 404		
7	S. Balesubraman	C-14 701		
8	Ashwan Keshme	C-14 802		
9	Sini Kesh	C-15 1102		
10	M.S. Sreekan	C-14 901		
11	Selish K. Pandey	C-14 101		very good
12	Pawan Kumar	C-14 104		5 Mile good - very
13	Ajay Srinivas	C-14 603		Good
14	A.K. Bhatt	C-14 704		
15	M. Kanti	C-14 604		V. Good
16	VIKAS KHERIA	C-14 801		V. Good with quality work
17	PK Bhatnagar	C-14 201		very low work at the
18	Niteek Tinsari	C-14 903		Need to exchange visad - 01/03/21
19	B.S. Rawal	C-14, 501		10/03/21 Security borders
20	Shobhit	C-14, 103		Shobhit

SNO	NAME	BLOCK / FLAT NO	MOR NO	DATE	PAGE	REMARK'S
21	VAIRAV KUMAR	C-14/302				VISIT Finishing is partial. Vasthav
22	DIVIK SHARMA	C-14/803				14/810, Lathi colony, N.Delli
23	(Ministry of Home Affairs)					
24						
25						

BLOCK - C-14 ~~BLOCK - B(02)~~ 14/03/2021
13-03-2021 DATE _____
PAGE _____

Its a dream house. Excellent अपने सपना (होने जैसा)

S.NO	NAME	PLAT NO	MOB. NO	REMARKS
1.	H. S Panwar	C/1002		Good construction at good angle in
2.	Ghanashyam Kv	C/902		Good support of Good construction
3.	Poonam	CIS/103		Very well show land
4.	Smil	CIS-1102		Looks Good
5	D.M.K. Srinath	CIS-703		
6	Vandana Choudhary	C-15 1004		Vandana C
7	M.P. Suresh	C-15 101		good labor m/s Suresh
8.	D.C. Pandey	CIS/804		Seen the labor and break m
9	K.N. Bharti	CIS/501		Vasant M/S
10				
11				
12				
13				
14				
15				
16				
17				

S.No. Flats No. Name of Owner Mobile No.

1	C-503	R. Das Loni
2		
3	C-1201	M. Singh
4		
5		
6		
7		
8		
9		
10	C 801	Y.P. Singh
11	C1002	P. Mannan
12	C17-201	Rohit
13		
14		
15		
16	C-17/1102	Arun K. Kumar
17	C-17/114	Gurpreet Singh
18	C-17/1204	R. C. SINGH
19		
20	C-17/1603	Gopal Kumar
21	C-17/502	K. L. GODIA
	702	Kanchan Bhandal
22		
23	C-17/301	Shyam Shank
24	C-17/902	Jaydish
25	C-17/804	S. K. Singh
26		
27		
28	C-17/1104	Suhank Maltoo
29	1004	Sanket K
30	C-204	Sandeep Rai

Remarks
Work is in advanced stage Possession is expected soon. Good quality of work observed

Height of railing of balcony for top floor needs to be increased for safety of children Finishing work require neat & clean work.

All good
All good
Finishing works to be done, some tiles are not aligned and fixtures to be fitted. Rest looking good.

Good work is going on in right direction to the satisfaction.
Singh

on good
Khandu 13/03/2021
Rohit 13/03/21

seems to be good by machine and repair required.

Good quality. Hope to see v. good finishing.
Quite good

22

Block - C-17

Date 13 03 2021
Page No.
Remarks

S.No.	Flats No.	Name of Abohee	Mobile No.	Remarks	S.No.	Flats No.	Name of Abohee	Mobile No.	Remarks
17	101	Amit Ranjan		Good					
18	303	Anil Kumar Sonkar		More					
19	403	Medhi Sharma		Sunlight is not proper at any time.					
20	601	Harender Singh		Sunlight is not available					
21	903	SK Mananty		↳ Satisfactory					